

DEC 18 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED  
035 NOV 21 AM 11:26

For corners in  
Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey

T 39N R 29W

T R

T R

T R

2. Property Controlling  
In Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

RECORDED  
DEEDS  
JAN 11 1996

Register of Deeds Stamp & File Number

I, Robert F. Perkins, in a field survey on Oct. 10, 1995,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

C-1 Northeast Corner, Section 6  
Post J. Mullett 1847  
Original Bearing Trees  
Sugar 12" N15°E 27 Lks.  
Hemlock 8" N42°W 14 Lks.

C-2 East  $\frac{1}{2}$  Corner, Section 6  
Post J. Mullett 1849  
Original Bearing Trees  
Y.Pine 18" N30°E 15 Lks.  
R.Oak 6" N61°W 18 Lks.

ACCEPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON

11-20-95

RFP

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

C-1 No Evidence of Original Corner or  
Accessories Found.  
Found Concrete Monument buried in Road  
Per Sheet 50-City of Norway Land Record.  
Corner Researched in 1994.

C-2 No Evidence of Original Corner or  
Assessories Found.  
Found 1" Iron Pipe that was placed over  
Concrete Monument (buried 36") in 1970.  
Corner appears on Sheet 5-F-City of  
Norway Land Record.  
Corner Researched in 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1 Placed Monument Box over Existing  
Monument.  
Set Stamped D.C. Remon. W.C. S85°E-28.00'  
Power Pole S34°E (M.B.) 40.22'  
Power Pole #71-2454 S57°W (M.B.) 44.30'  
Lynn 3" N79°W (M.B.) 82.75'  
Carsonite Marker 0.3' East of W.C.

C-2 Placed Monument Box over Corner.  
Corner Recorded in 1995.  
See Liber 2, Page 145 for Witnesses.

Signed by Robert F. Perkins

Date Nov. 1995

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971  
REVISED MAY 14, 1975  
REVISED JAN., 1983

