

SURVEY &  
REMONUMENTATION

DEC 18 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED  
1995 NOV. 21 AM 11:26

For corners in  
Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey

T 39N R 29W

F-1

T R

F-3

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Section

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Register of Deeds Stamp & File Number

I, Robert F. Perkins, in a field survey on Oct. 11, 1995,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

F-1 North  $\frac{1}{4}$  Corner, Section 4  
Post J. Mullett, D.S. 1848  
Original Bearing Trees  
Cedar 8" N71°E 17 Lks.  
Cedar 4" N10°W 24 Lks.

F-3 South  $\frac{1}{4}$  Corner, Section 5  
Post J. Mullett, D.S. 1849  
Original Bearing Trees  
Cedar 4" N17°E 12 Lks.  
Hemlock 6" S30°E 14 Lks.

ADOPTED BY THE DICKINSON COUNTY  
SURVEY PEER GROUP AS THE OFFICIAL  
CORNER UNDER MICHIGAN PUBLIC ACT  
345 OF 1990 AT A MEETING HELD ON

11-26-95

R.F.P.

COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-1 No Evidence of Original Corner  
or Accessories Found.  
Found 1" Sq. Bolt buried 5" in Road  $\frac{1}{2}$   
at Old East-West Fences (Corner Re-  
corded as F-13 T40N-R29W in 1984).  
Corner Researched in 1994.

F-3 No Evidence of Original Corner or  
Accessories Found.  
City of Norway Land Record (Sh. 11-H)  
indicates Iron Pin in Concrete at Old  
Fence Corner.  
Corner Researched in 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F-1 Accepted above described Corner.  
New Witnesses  
Set 3" Stamped D.C. Remon. W.C.,  
N80°W (M.B.) 20.00'  
Set 3" Stamped D.C. Remon. W.C.,  
S80°E (M.B.) 20.00'  
Cedar 4" S66°W (M.B.) 55.00'  
X Cut on 4' Boulder N68°E (M.B.) 33.22'  
Set Carsonite Stake at Witness Corners

F-4 Found and Accepted above described Monument.  
New Witnesses  
X Cut in 1' Boulder N13°W (M.B.) 8.52'  
X Cut in 3' Boulder N74°W (M.B.) 71.75'  
X Cut in 2' Boulder S76°E (M.B.) 18.31'  
Apple 8" S35°E (M.B.) 35.46'  
Placed Carsonite Marker 1.83 Feet North  
of Corner.

Signed by

Robert F. Perkins

Date Nov. 7, 1995

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

