MAR 0 3 1998

SEC	1	ON	
⊃E/	<i>)</i>	\sim 1.4	

LAND CORNER RECORDATION CERTIFICATE

RECORDED

Filing	Requirement	of	Act	74,	Mich.	P.A.	1970
	.,			,			

F	Filing Requirer	nent of Act 74, Mich. P.A. 1970	1797 DEC 10 PM 3: 57
For corners in Dickinson	Located In:	Corner Code #	525 13 11 5 5,
Norway Twp.			REGISTER OF DREDS
Public Land Survey	T <u>40N</u> R <u>29W</u> T R T R T R	E-1 E-2	HON ME 12 CHEST AND
Property Controlling in Section	ST R ST R		
Miscellaneous Property in Section	S T R S T R		gister of Deeds Stamp & File Number
4. Let No, F	Recorded Plat		~ A B C D E # C H ! X !
			2 6 5 6 1 3 1 2 1 1
			3
. Dalame D. Dawledon		Sant 22 - 97	4 7 8 9 10 11 12
do horeby certify that under re-	, in a field survey on	of 1970, the comer points mentioned	5
		es therefore as required in the current	6 18 17 16 15 14 13
manual of survey instruction	s of the United States Departmen	nt of the Interior, Bureau of Land	7-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1
-	and the second s	er points mentioned in lines 3, 4 and	8 19 20 21 22 23 24-
		rd of Professional Surveyors or by a	9
as expressed below:	ionariso, re-established, mondifierite	a, 10-110mantented, 10004e160, 100nd	10 30 29 28 27 26 25
NOTE: Not more than 4 co	rners, all in the same town and ra	ange may be recorded	11-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-
on this certificate.	more, and the define town are a	orgon man us recorded	12 -31 32 33 34 35 36-
			13
A. Description of original	monument and accessories and	d/or subsequent restoration:	
E-1 Northeast	Corner, Section 5	E-2 ½ Corner	to Sections 5/4
Post by J	.H. Mullett, D.S. 1848	Post by J	.H. Mullett, D.S. 1849
Original	Bearing Trees		Bearing Trees
	4" S55°W 25 Lks.		" N12°W 05 Lks.
Hemlock l	0" S57°E 40 Lks.	Cedar 8'	CIPTED BY THE DICKINSON COUNTY RVEY PEER GROUP AS THE OFFICIAL

- COUNTY REPRESENTATIVE B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - No Evidence of Original Corner or Accessories Found. Found 1" Iron Pipe with 4" D.N.R. Brass Cap set by D.C. DeLaMater, RLS in 1955. No Witnesses available at that time. (Old Report #61)
- Found Remains of Orginal Pine B.T. E-2 Stump N12°W 3.3'. Found 1" Iron Pipe with 4" D.N.R. Brass Cap Set by D.C. DeLaMater, RLS in 1955. 1955 Bearing Trees: W. Ash 9" N13°E 31 Lks. Y.Birch 24" N60°W 25 Lks. (Old Report #53)

345 OF

CURRER UNDER MICHIGAN PUBLIC ACT 1990 AT A MEETING HELD ON

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - E-1 Found and Accepted above described Monument. New Witnesses: Maple 8" S21°W (M.B.) 24.49' Nail/Tag S66°E (M.B.)

Maple 7" 16.09 Nail/Tag N28°E (M.B.) Maple 6" 34.98' Nail/Tag Maple 3" N79°W (M.B.) 17.70' Nail/Tag Carsonite Marker South 1.1

Found and Accepted above Described Monument.

New Witnesses:

Maple 3" N46°E (M.B.) 8.12'Nail/Tag Maple 3" S25°E (M.B.) 46.86'Nail/Tag Maple 8" N83°W (M.B.) 22.13'Nail/Tag Ironwood 3" S12°W (M.B.) 17.43'Nail/Tag North 1.0

Carsonite Marker

12027 Surveyor's Michigan License No.

Nov. 19, 1997

ROBERT F. ERKINS S/ONAL S

ATE OF MICHIGA

Date

E-2