

DEC 18 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

1995 NOV 21 AM 11:27

For corners in

Dickinson
(County)

Located In:

Corner Code #

- | | | | | | |
|------------------------------------|---|------------|---|------------|------|
| 1. Public Land Survey | T | <u>40N</u> | R | <u>29W</u> | E-11 |
| | T | | R | | E-12 |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | | R |
| | S | | T | | R |
| 3. Miscellaneous | S | | T | | R |
| Property in Section | S | | T | | R |

RECORDS
11-20-95

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert F. Perkins, in a field survey on Oct. 9, 1995, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-11 Northeast Corner, Section 32
Post J. Mullett 1849
Original Bearing Trees
Maple 8" S45°E (M.B.) 13 Lks.
Aspen 12" N40°W (M.B.) 40 Lks.

E-12 East $\frac{1}{4}$ Corner, Section 32
Post J. Mullett 1849
Original Bearing Trees
Cedar 15" N52°E (M.B.) 29 Lks.
Cedar 10" S52°W (M.B.) 34 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11 No Evidence of Original Corner or Accessories Found.
City of Norway Land Record indicates Concrete Monument buried 1" in Road E.
Corner Recorded in 1984
However, Bearing Trees are Erroneous.

Corner Researched in 1994.

E-12 No Evidence of Original Corner or Accessories Found.
Concrete Monument in Asphalt Road with 2 bearing Trees Recorded in 1984.
Corner Researched in 1994.

ACCEPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON

11-20-95

RFP

COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-11 Placed Monument Box over Existing Concrete Monument.
New Witnesses
Set 3" Stamped D.C. Remon. W.C.
Carsonite Marker N07°E (M.B.) 34.30'
Maple 5" S29°W (M.B.) 37.77'
Balsam 2" S30°E (M.B.) 38.05'
Power Pole (No #) N66°W (M.B.) 87.38'
Power Pole (No #) N77°E (M.B.) 79.34'

E-12 Placed Monument Box over Concrete Monument noted above.
New Witnesses
Set 3" Stamped D.C. Remon. W.C. and
Carsonite Marker N55°W (M.B.) 27.80'
P. Pole S32°W (M.B.) 70.48'
N.W. Corner Foundation (Hse. #2698),
S85°E (M.B.) 38.54'.
S.W. Corner Foundation S26°W (M.B.) 79.40'

Signed by

Robert F. Perkins

Date Nov. 7, 1995

Surveyor's Michigan License No. 12027

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS

