

MAY 07 1997

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

DEC 18 AM 11:15

For corners in

COMMISSION

Dickinson

(County)

Located in:

Corner Code #

1. Public Land Survey

T 40N R 29W

J-7

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

REGISTER OF DEEDS
DICKINSON COUNTY
IRON MOUNTAIN, MI 49801

7

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Michael Mileski, in a field survey on 25 October, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J-7; One-quarter Corner common to Sections 14 and 23, T40N, R29W;

See back of form.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-7; One-quarter Corner common to Sections 14 and 23, T40N, R29W;

Found a 1" x 42" galvanized iron pipe with a 4" brass cap as set by Mr. DeLaMater in 1954 inside of a 2" diameter iron pipe, firmly set, projecting 20" above the ground. Mr. DeLaMater's monument was found to be in agreement with his new bearing trees as described in Part A. Replaced Mr. DeLaMater's monument with a standard county monument described in Part C. Accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

J-7; One-quarter Corner common to Sections 14 and 23, T40N, R29W;

Drove the 2" diameter iron pipe to a point 4" above the ground and set on the south side a 5/8" x 36" aluminum rod with a 3" aluminum cap stamped as to location.

i) Set 7" spike	S/side	10" Cedar	N73°E	21.78'
ii) Set 7" spike	NE/side	7" Tamarack	S56°E	40.73'
iii) Set 7" spike	SE/side	14" Cedar	S40°W	20.65'
iv) Set 7" spike	NE/side	11" Cedar	N52°W	50.70'
v)		Location Post	North	3.0'

(i) is a DeLaMater new bearing tree and is further described in Part A.
(ii), (iii), and (iv) are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes as well as a band around the tree at the upper blaze are painted red.

Signed by Michael Mileski

Surveyor's Michigan License No. 39091

Date 3 DEC 1996

Bk. 17M pp 5 & 6

