LAND CORNER RECORDATION CERTIFICATE

	Filing	Requirement of A	ct 74, Mich. P.A. 19	70		
For corners in			1			
Dickinson (County)	Located In:	Corner Code #				
1. Public Land Survey	T_40NR_ T_40NR_ TR_	29N				
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_			Register of	Deeds Stamp &	File Number
4. Lot No, Record	ded Plat	· · · · · · · · · · · · · · · · · · ·	<u>.</u> .	A B C D	EFGH	IJKLM
5. Filvate Claims				2 6 5	,	
	I2 J2	Oct 22 2000 Sep 11 2000		3		
l Stenhan J Szyszkoski	in a field survey on _	19 dx	hereby state that under	4 - 7 6	9—10—	11-12-
requirements of P.A. 74, Michigal conformance with regulations and	n P.A. of 1970, the corner	points mentioned in line	s 1 and 2 above were in	5	_ _ _	
United States Department of the In	nterior, Bureau of Land Mai	nagement or by a decree	of a Court of Law and /or	6 -19-1	71615	14-13-
that the corner points mentioned Board of Land Surveyors or by				7	- - - -	
recovered, found as expressed be	iow:			8 19-2	021	2324
NOTE: Not more than 2 com	ers, all in the same town	and range, may be rec	orded	9		
on this certificate.				10 30 - 2	9-1-28-27-	26 25
				11		
				12 31 3	2 33 34	35 - 36
(J2) Center of Section 2. N (I2) Quarter corner common t 35.50 Begin to descend. 40.0 feet88.40 intersected 4th	o Sections 2-3. Estat O Set quarter section	plished in 1849 by Ja post, Birch 6 S26E	ames Mullett: North b 13, Birch 6 S68W 18.	etween Sec. 2 & 42.20 Brook 02	330.00 Summit rapid C SE at foo	t 50 feet. ot of hill 50
B. Description of corner evid	dence found and/or met	thod applied in restoring	ng or reestablishing cor	rner:		
(J2) Established the corner (I2) Original post and acces features along the southerly observed along the portion t made, particularly in the rorather reestablish the corne line of mean true bearing be	sories were not recover 50 chains of this li to the north, where the ougher northern 1/2 mi er at record distance	ered. This mile mea ne check roughly wit e terrain becomes mo le of this line. Co south (2.20 chains)	sures 310' longer tha h the record. Substa re severe. I believe nsequently, I do not from the creek bed no	an the original antial difference that the orgin proportion the oted in the reco	es with the reco al measurements excess throughou	rd were were poorly t the mile but
C. Description of monument (J2) Set 1"ID iron pipe with MDNR cap. Blazed and scribe 9" Cedar N86E 37.4" 12" Cedar S24E 19.8' 9" Cedar S71W 41.9' 8" Cedar N6W 26.8' Sqd cedar post adjacent. Bu magnetic. Distances are to lower blaze.	n 4" aluminum (I ed: MD "C1/4 BT" 5" do 6" do 6" do 3" earings are P1 notch in 8e	ries established to per 2) Set 1"ID iron pip NR cap. Blazed and Aspen MOIW 12.1' * Sugar S78E 27.2' * Sugar S53E 26.7' R. Maple S43W 15.6' aced sqd sugar post arings are magnetic. stance. Distances a	- with 4" aluminum	* 8	OF MAN	* *
Signed by	1. 18 - 00 1	hol:	Date	1/16/	01	

33986

Surveyor's Michigan License No.