

RECORDED

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

1999 NOV 29 AM 10:31

For corners in

Dickinson

(County)

Breitung Twp.

Located In:

Corner Code #

1. Public Land Survey

T 40NR 30W

E-6

T R

D-5

T R

T R

2. Property Controlling
in Section

S

T R

SURVEY &

3. Miscellaneous
Property in Sec.

S

T R

REMONUMENTATION

S

T R

MAR 24 2000

REGISTER OF DEEDS
DICKINSON COUNTY
RONALD E. [illegible]

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____ SECTION _____

I, Robert F. Perkins, in a field survey on March 9, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5		4		3		2		1	
3													
4	7			8		9		10		11		12	
5													
6	18			17		16		15		14		13	
7													
8	19			20		21		22		23		24	
9													
10	30			29		28		27		26		25	
11													
12	31			32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

E-6 East $\frac{1}{4}$ Corner, Section 17
Post by J.H. Mullett, D.S. 1849
Original Bearing Trees
Aspen 12" S36°E 15 Lks.
Aspen 12" N14°W 18 Lks.

D-5 $\frac{1}{4}$ Corner $\frac{8}{17}$
Post by J.H. Mullett, D.S. 1849
Original Bearing Trees
Aspen 4" N74°W 07 Lks.
Aspen 4" S35°E 09 Lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-6 No Evidence of Original Corner Found.
Corner research under Contract #2, 1998
Found 2" Sq. Headed Bolt at Old Fence
Intersection \pm 2619' South of N.E. Corner,
Section 17. Corner indicated on 1934
D.C.R.C. Map File A-10, No. 36, Sheet #3.

D-5 No Evidence of Original Corner
or Accessories Found.
Found Sq. Iron Bolt \pm 1' below Road
Surface as shown on Dickinson Co.
R.O.W. Map File A-10, No. 36, Sheet 3.
Corner used and accepted on prior
Surveys.

ADOPTED BY THE DICKINSON COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT
345 OF 1990 AT A MEETING HELD ON
11-23-99

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-6 Accepted Bolt described in E-6 above as
Best Remaining Evidence of Corner
Location. Replaced Bolt with 2 $\frac{1}{2}$ " Stamped
Cap, D.C. Remon. Marker.
New Witnesses
Ironwood 3" S32°W (M.B.) 22.79'
Ironwood 5" N45°W (M.B.) 15.48'
Ironwood 4" N59°E (M.B.) 42.88'
Maple 3" S79°E (M.B.) 36.66'
Placed Carsonite Marker North 0.85'

D-5 Accepted Bolt described in E-6 above
as Best Remaining Evidence of Corner
Location. Set 2 $\frac{1}{2}$ " Stamped D.C. Remon.
Marker over Bolt, in Monument Box.
New Witnesses
Maple 8" S45°W (M.B.) 106.65' Spike/Tag
R. Pine 14" N41°W (M.B.) 135.25' Spike/Tag
P. Pole #79-27988 N50°E (M.B.) 49.11' "
X Cut Top 4' Boulder S45°E (M.B.) 59.25' "X"
Corner is 14.6' East $\frac{1}{2}$ Co. Road & 11.6'
South $\frac{1}{2}$ Collins Rd.
Date Nov. 5, 1999

Signed by Robert F. PerkinsSurveyor's Michigan License No. 12027