MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_11 NR_27 W

	Dickinson COUNT	Y
DESCRIPTION OF CORNER	Section corner common tomsections 29,30,31 and 32 MONUMENT 1" pipe with 4# brass cap	
DESCRIPTION OF CORNER WITTNESSES TO CORNER	Cedar 10" N 70 E 18 links, marked S 29 NBT	
	Cedar 7" N 24 W 37 1/2 links, marked S 30 NBT Cedar 6" S 80 W 37 linksm marked S 31 NBT	
Dastances measured from	center of brass cap to NBT notch.	

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two original cedar bearing trees, one in excellent condition and one in good condition (down). Wood post in place at fence corner.

Corner was found while cruising timber in this area.

Corner was placed and witnessed on 12 June 1957 with J. Doyle Voice.

SURVEYORS SEAL