

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
Dickinson

(County)

Located In:

Corner Code #

1. Public Land Survey T 42N R 28W A3
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Stephan J. Szyszkoski, in a field survey on November 14, 1994, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A3) Corner common to Sections 6-7 T42N-R28W and 1-12 T42N-R29W. Corner previously re-monumented at the original position and filed in 1957 by Billy D. Buckler, RLS. Placed 1" pipe with 4" brass Michigan Dept. of Conservation cap and the following NBTs: 24" W. Pine stump N77E 36 links, 7" Balsam S74W 54 links. Buckler noted original W. Pine bearing tree stumps S54W 41 links, and N27E 48 links. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A3) Found and accepted Buckler's monument as described, at record bearing and distance from his 1957 witnesses: the W. Pine stump now rotted, the balsam in good condition. Recovered the original BT stump noted by Buckler N27E 31.7' in proper relation to the corner. Left the monument in place and marked 4 new bearing trees as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A3) Found 1" iron pipe with 4" brass
Michigan Dept. of Conservation cap.
Blazed and scribed the following new
bearing trees:

5" Maple N79W 31.7' "S1 NBT"
12" Maple S05W 42.7' "S12 NBT"
12" Spruce S08E 49.0' "S7 NBT"
8" Maple S84E 57.8' "S7 NBT"

Bearings are magnetic.



Signed by Stephan J. Szyszkoski

Date 2-22-95

Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources - Forest Management Division.