LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

- 1

For corners in

Dickinson	_ Located In:	Corner Code #											
(County) West Branch Township 1. Public Land Survey	T R R												
2. Property Controlling in Section	S 26 T 43N R 27W S 26 T 43N R 27W S T R	13 16											
3. Miscellaneous Property in Sec.	S T R R			Regi	ster of	Deed	is Sta	s qmı	i File	e Nu	ımb€	er_	
4. Lot No. , Red	corded Plat		<u>, λ</u>	В	C D	E	F G	H	I.	å	K.	L	М
5. Private Claims			<u>,</u> [Ţ_		10			\bot	_j.		_ [- 1
	8/21/201	2AD	٦L	Ĭ		JH.	Ì	Ĭ	\perp		\perp	Ţ	
ı, Jeremy J. Pipp , i	in a field survey on 8/21/201	2AD do hereby state		<u> </u>	\perp		ا .	10	丄	_17	\bot	_ _12	٠
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2													
above were in conformance with regulations and rules therefore as required in the current manual of survey													
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6													
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7													
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, a 19 20 21 22 23 24													
re-established, monumented, recovered, found as expressed below:							寸						
	and the same same and range	a may be recorded	10	-30- 	29		-28 	27		26	•	—25 	<u> </u>
NOTE: Not more than 2 corners, all in the same town and range, may be recorded									1	•	寸	_	
on this certificate.			12	-31 	32		-33 		'	—35 	+	36 	. —

- A. Description of original monument and accessories and/or subsequent restoration:
- (13) Southeast One-Sixteenth corner of Section 26. Not set in original survey, no evidence of subsequent establishment.
- (16) East One-Sixteenth corner common to Sections 26 and 35. Found Terrance Wanic PS#44296 Plastic capped 5/8 inch Iron Pin.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (13) Corner position established at the intersection of the South and East One-Sixteenth lines of Section 26.
- (16) Corner position calculated mid-point and on-line between the South One-Quarter corner and the Southeast corner of Section 26. Found Capped Rebar checked well for position was accepted. Set MDNR monument in place of said existing monument.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13)	DNR monument	(16) DNR monument			
6" Cherry	N89E 42.66' (1/16S,BT)	10" Tw. Cedar S82E 15.75' (1/16S,BT)			
5" Cherry	S25E 21.30' (1/16S,BT)	9" Cedar S05E 13.22' (1/16S,BT)			
5" Cherry	S56W 53.62' (1/16S,BT)	6" Cedar S89W 28.04' (1/16S,BT)			
5" Cherry	N27W 13.83' (1/16S,BT)	6" Cedar NO8W 35.32' (1/16S,BT)			
	are blazed, scribed, and	All trees are blazed, scribed, and			
	Measurements are to nail in	per components are to nail in			
side of tree, bearings are magnetic.					
Signed by		August 29, 2012			

Surveyor's Michigan License No.

5044

For the Michigan Department of Natural Resolution

FOR OPPROVED BY A FIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

80447 Revised May 14, 1975

Revised Jan., 1983 Rervised Oct., 1995