MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T_43_N NR_27_W

			Dickinson COUNT
DESCRIPTION	OF	CORNER	1/4 corner between sections 16 and 21
DESCRIPTION	OF	CORNER	MONUMENT 1" iron pipe with 4" brass cap.
WITTNESSES	то	CORNER	Cedar 16" N 30 E 29 links marked 1/4 S NBT
			Cedar 12" N 70 W 26 1/2 links, marked 1/4 S NBT
			Cedar 10" S 56 W 32 links, marked 1/4 S NBT

Distances measured from center of brass cap to NBT notch.

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from one original cedar bearing tree 10" N 37 E 10 links down, in fair condition. Scribe marks plain on both description and BT blaze, and from one original cedar bearing tree 12" S 54 W 27 links in poor condition, down and badly rotted. Found axe marks in remains but no scribe marks.

Corner was found while examining road application in this area, with Clarence Ryberg.

Corner was placed and witnessed on 28 October 1958 with Norman J. Karsten.

SURVEYORS SEAL

SIGNED_Henry_S. Peterson REGISTERED LAND SURVEYOR