LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson	_ Located In:	Corner Code #		
(County) FELCH TOWNSHIP				
//	T 42N D 20N	D10		
1. Public Land Survey	T 43N R 29W	D10		
	<u> </u>			
3 Para antis Cantrallia a				
2. Property Controlling	STRR			
in Section	S 29 T 43N R 29W	09		
3. Miscellaneous	STR			
	S T R			
Property in Sec.	SI		Register of Deeds Stamp & File Number	
4. Lot No. Recorded Plat				
5. Private Claims			ABCDEFGHIJKLM	
	2/26/2013	RAD	2 - 6 - 5 - 4 - 3 - 2 - 1 - 1	
A Joromy I Dian			3	
, Jeremy J. Pipp , ii			4 - 7 - 8 - 9 - 10 - 11 - 12	
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2				
above were in conformance with regulations and rules therefore as required in the current manual of survey				
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of 6 18 17 16 15 14 13				
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with 7 the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 8 19 20 21 22 23 24				
re-established, monumented, recovered, found as expressed below:			8 -19 -20 -21 -22 -23 -24	
to communication, monunicates, recoveres, round as expressed below.			9	
			10 30 26 27 26 25	
			11	
on this certificate.		12 31 32 34 35 36		
			13	

- A. Description of original monument and accessories and/or subsequent restoration:
- (D10) Center One-Quarter Corner of Section 29. Not set in original survey. 1992: Michigan DNR (Keith Sackett, PS#19006) Set 1" pipe with 4" Aluminum cap witnessed by: 8" Sugar (Sugar per record; actually a Cedar) N10E 36.1', 4" Sugar S13E 32.2', 5" Sugar \$89W 15.1', 3" Sugar N54W 20.5'.
- (09) Center-East One-Sixteenth corner of Section 29. Not set in original survey, found 1 1/4" pipe N33E, 16.26 feet from calculated position; not accepted.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (D10) Accepted Found MDNR Monument and three living witnesses as being established at the intersection of the North-South and East-West One-Quarter lines of Section 29.
- (09) Corner position established mid-point and on-line between the Center One-Quarter corner and the East One-Quarter corner of Section 29.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D10) DNR monument	(09) DNR monument
EX. 13" Cedar NO8E 36.88' (1/4S,BT)	10" Maple N10W 36.92' (1/16S,BT)
4" Tamarack S46E 3.53' (1/4S,NBT)	11" W. Birch S64E 12.12' (1/16S,BT)
EX 6" Maple \$85W 15.47' (1/4S,BT)	9" W. Birch S07W 7.69' (1/16S,BT)
EX 5" Maple N56W 20.51' (1/4S,BT)	7" Maple N70W 41.98' (1/16S,BT)
All trees are blazed, scribed, and	All trees are blazed, scribed, and
painted. Measurements are to nail in	painted Measurements are to nail in side of tree, bearings are magnetic.
side of tree, bearings are magnetic.	stile of tree, leanings are magnetic.
	The state of the s

Surveyor's Michigan License No.

PROFESSIONAL For the Michigan Department of Natural Resources

orest Resource Origina

JEREMY Date 9पाप

> STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 Revised May 14, 1975

July 22, 2013

20190

20189

Revised Jan., 1983 Rervised Oct., 1995