

# LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

## DICKINSON COUNTY

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____	T. 43 <sup>N.</sup> <del>36</del> <sup>W.</sup> R. 29 <del>W.</del> <sup>W.</sup>	C2, D5
2. PROPERTY CONTROLL- ING IN SECTION 29_____	T. 43 <sup>N.</sup> <del>36</del> <sup>W.</sup> R. 29 <del>W.</del> <sup>W.</sup>	10
3. MISCELLANEOUS PROPERTY IN SECTION_____	T. _____ <sup>N.</sup> <del>S. R. _____ <sup>E.</sup> <del>W.</del> <sup>W.</sup></del>	
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND  
FILING NUMBER

I, Keith L. Sackett, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on See Below, 19\_\_\_\_, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on \_\_\_\_\_, 19\_\_\_\_, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner C2: Original monument and accessories not found.  
 Corner 10: Not set on original survey nor subsequently apparently. Found old cruisers post and paint line west 39 ft.  
 Corner D5: Original monument and accessories not found.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner C2: Restored 5-11-81 by proportion between section corners north and south.  
 Corner 10: Established 5-12-81 on line midway between corners north and south.  
 Corner D5: Restored 5-14-81 midway on line between corners east and west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner C2: Set 1" I.D.x32" iron pipe with 4" alum. cap.  
 10" Spruce S36°W 31.3 ft. 1/8S,NBT  
 8" Tamarack N55°W 30.2 ft. 1/8S,NBT  
 Corner 10: Set 1" I.D.x36" iron pipe with 4" alum. cap.  
 6" Sugar N78°E 17.9 ft. 1/16S,BT  
 6" Sugar N05°W 14.2 ft. 1/16S,BT  
 5" Sugar S52°W 24.5 ft. 1/16S,BT  
 Corner D5: Set 1" I.D.x32" iron pipe with 4" alum. cap. Monument falls in middle of farmed field. Only trees around were dead elm. Placed large squared post marked 8, 17, 1/4.

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

SURVEYOR'S MICHIGAN REGISTRATION NO. \_\_\_\_\_

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY \_\_\_\_\_ DATE \_\_\_\_\_

APPROVED AND SIGNED BY Keith L. Sackett DATE 10-22-81  
 CHIEF OF SURVEY PARTY  
 MICHIGAN REGISTERED LAND SURVEYOR  
 Keith L. Sackett  
 Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 19006