

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County)	Located In:	Corner Code #
1. Public Land Survey	T 44N R 30W	F9
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 08/10/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F9) Quarter corner common to Section 21 and 28. 1848 - Established by John Burt Deputy Surveyor on
the Section line between Section corners 39.85 chains east and 39.86 chains west. Set cedar post.
Lynn 12 S25E 33 links, Y.Birch 18 N21W 32 links. June 9, 1934 - Noted in Dickinson County Road
Commission notebook in "Compass Traverse of Present Road Sawyer Lake to New Bridge at Michigamme
River" by E.R.Nelson and W.C.Johnson, Pages 37-39. Corner "1/4 cor. 21-28 44-30" is given as a
sideshot from the main traverse and is not further described. Dist. to E9 given as "approx. 2680'".
2005 - Corner reestablished by R.R.Spear PS by single proportionate measurement following searches
which failed to recover any monumentation at the corner position. Set 3/4" dia.x3' long alum. rod
with 3-1/4" cap (Dickinson County monument). 9" Balsam S64W 36.14', 10" Maple S87E 113.02', 7"
Balsam S23W 79.01', U.pole S65E 10.26', carsonite post North 1.0'. Corner accepted 11-22-2005 by the
Dickinson County Survey Peer Group and recorded in L4, P250, Land Corner Records, Dickinson County.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F9) The original post and accessories were not recovered. Found a 1-1/2" I.D. iron pipe projecting
9" above ground, firmly set, 2668.17' east of corner E9 of record and approx. 2643.1' west of corner
G9 of record. The pipe is on the N'yly extension of a long-standing line of occupation south of
Newburg Road, consisting of a very old and unmaintained fence and field stone row with field and
timber type change on the east and west. This line was easily traced for approx. 600' south from the
corner position, at which point it is completely obliterated. Computation of the 1934 compass
traverse between this pipe and the NW corner of Section 21 yields a closure of 1 part in 1747 which
seems sufficiently precise to support the speculation that the pipe is in the 1934 position. No
description of the corner monument nor witnesses were found in the Road Commission field books or on
old plans. I accepted the pipe as the best available evidence of the position of the original
corner. The 2005 monument of record was found N 30 deg 51'W (true) 23.87' distant and was not
accepted as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F9) Found 1-1/2" I.D. iron pipe projecting 9".
Set measuring nail with MDNR tag in the side of:
Old power pole cut 5' tall N06E 15.5'
6" Elm S72E 37.9' mrkd "1/4S NBT"
8" Elm S14W 9.1' do
6" Sugar N87W 27.3' do
Set sq'd cedar post 1 ft. north
Bearings are magnetic.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/9/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971