

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Dickinson (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 21 T 44N R 30W	13
	S 21 T 44N R 30W	9
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

A	B	C	D	E	F	G	H	I	J	K	L	M
1												
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

I, Stephan J. Szyszkoski, in a field survey on 08/11/2010 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 21) Southeast 1/16 corner, Section 21. Not established in the original survey. Found no
subsequent record.

(9-Sec. 21) East 1/16 corner, Section 21. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 21) Established the corner at the intersection of straight lines connecting opposite 1/16
corners.

(9-Sec. 21) Established the corner midway and on a straight line between Center of Section 1322.69'
west and Quarter corner (as reestablished in 1991 by Edward Kazianka RLS) 1322.69' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
16" Sugar S70E 28.9' mrkd "1/16S BT"
8" Sugar S46E 27.1' do
6" Maple S15W 16.4' do
16" Maple S69W 36.6' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Sugar N56E 5.4' mrkd "1/16S BT"
4" W.Birch S30W 5.3' do
8" Sugar N89W 33.5' do
7" Sugar N03W 15.3' do
Set sq'd cedar post adjacent.
Bearings are magnetic. The mon. leans 0.2' S.
The top center of the cap marks the corner
position.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 12/09/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

