

## GLADWIN COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 169

For corners in

GLADWIN

(County)

Located in:

Corner Code #

1. Public Land Survey

T 18N R 1W

C-3

T R

T R

T R

2. Property Controlling  
in Section

S

T R

S

T R

3. Miscellaneous  
Property in Sec.

S

T R

S

T R

STATE OF MICHIGAN

GLADWIN COUNTY

FILED - Remonumentation

17 OCT 97 1:19 P.M.

BONNIE K. HOUSE

REGISTER OF DEEDS

Register of Deeds Stamp &amp; File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, MARK R. ROBISON, in a field survey on May 6, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

1877 T. Gale Merrill

Set Post

Wit-(1)S88W 7 links 8" Black Ash

(2)N48E 12 links 9" Cedar

1960 Edmands Eng.-Railroad maps

Set iron 4.7' N of C/L of R.R. Grade

Wit-(3)8" Elm 17.3' E.N.E.

(4)Iron in fence line 124.61' East

(5)Fence Cor 65.3' S.S.E.

(6)Iron in fence line 49.42' North

(7)Fence Cor 48.15' N

1992-93 Lapham-4 surveys

Wit-same as (3),(4),(5),(6)&amp;(7)

Misc. Lapham working drawings

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 3/8" x 14" rerod 4.7' North of centerline of old railroad grade on line with fence to North. Found 3/8" rerod 4.7' South in centerline grade. Found (7); (fence corner) poor condition, North 48' +/- Set Gladwin County Re-mon in place of found 3/8" x 14" rerod 4.7 ft. North of centerline.

APPROVED LAND CORNER

P.A. 345 of 1990

Gladwin County

See dossier for detailed report.

Co. Rep.

Date

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-3: Corner common to Sections 5, 6, 7, &amp; 8.

Set 5/8" x 36" rerod with Gladwin County Re-mon Cap marked P.S.#27458.

Witnesses:

South 4.7' - 3/8" rerod

South, top metal Anchor Post, 44.40'

N45W Triple 10" Basswood, nail &amp; tag, 39.20'

N35E Twin 8" Basswood, nail &amp; tag, 44.82'

SURVEY &  
REMONUMENTATION

JAN 0 8 1998

SECTION

Signed by

Surveyor's Michigan License No. 27458



Date

10-7-97