

SURVEY & MONUMENTATION

JAN 17 1996

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 80

For corners in

GLADWIN
(County)

Located In:

Corner Code #

1. Public Land Survey

T18N R 1W

G-8

2. Property Controlling
in Section

S
S

T
T

R
R

3. Miscellaneous
Property in Sec.

S
S

T
T

R
R

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

STATE OF MICHIGAN
GLADWIN COUNTY
FILED-REMONUMENTATION

26 DEC 95 10:52 A.M.

BONNIE K. HOUSE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, PAUL B. LAPHAM, in a field survey on MAY-NOVEMBER, 19 95 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

1877 T. GALE MERRILL
POST
WIT.-(1)BEECH 13" S32°W 11
(2)D.O. N16°E 28

NO DATE PAUL LAPHAM
SET 1/2" IRON
WIT.-(6)EAST CONC. MON. 40.08'
(7)S35°W 75.89' P.K. IN P.P.

1978 PAUL LAPHAM
FOUND 1/2" IRON
WIT.-(3)WEST 24.95 FENCE COR.
(4)S30°W 64.3' TELE RISER
(5)EAST 35.5' FENCE COR.

1979 SURVEY BY DUNTON
NO WITNESSES
EDMANDS
WORK DWGS.
NO WITNESSES

1994 WITNESSES FOR GLADWIN CO. ROAD COMM.
FOR ROAD CONSTRUCTION
FOUND 1/2" IRON
WIT.-(8)EAST FENCE COR. 35.60'
(9)EAST CONC. MON. 40.05'
(10)S35°E 4" RED PINE 70.22'
(11)S30°W P.P. 75.87'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND P.K. NAIL IN C OF ASPHALT ROAD, BENT & BEAT UP, RESET FROM WIT. # (8), (9), (11).
FOUND WIT. # (6), REC. 40.08', MEAS. 40.05', FOUND WIT. # (5) REC. 35.5', MEAS. 35.5'.
SLIGHT LEAN IN POST MEAS. G-7 TO G-8 PAUL LAPHAM 2637.08', EDMANDS 2636.67', DUTON 2638.35'.
EXCAVATED UNDER WIT. FOUND 1/2" IRON 1' BELOW SURFACE, TOP BENT FIT WIT.

This Corner established in Gladwin County Remonumentation Program.

See dossier for detailed report.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-8: CORNER COMMON TO SECTIONS 21 & 22
SET 5/8"x36" RE-ROD WITH 3" GLADWIN COUNTY RE-MON CAP IN MONUMENT BOX MARKED P.S. #9433

WITNESSES:
EAST 35.60' - FENCE CORNER (SPIKE)
EAST 40.05' - CONCRETE MONUMENT
S35°E 70.28' - NAIL & TAG IN 4" RED PINE
S30°W 75.87' - NAIL & TAG IN POWER POLE
WEST 70.45' - NAIL & TAG IN 4" POPLAR
NORTH P.K. NAIL 2.0'
EAST P.K. NAIL 2.0'



Co. Rep. J. H. Meyer
Date 12/14/95

Signed by Paul B. Lapham
Surveyor's Michigan License No. 9433

Date 12-22-91