

SURVEY &
REMONUMENTATION
APR 07 1995
COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

PAGE 59

For corners in

GLADWIN
(County)

Located In:

Corner Code #

1. Public Land Survey

T 18N R 1W

K-3

2. Property Controlling
in Section

S T R

3. Miscellaneous
Property in Sec.

S T R

STATE OF MICHIGAN
GLADWIN COUNTY
REGISTER

28 DEC 94 3:01 P.M.

ROBERT C. HOUSE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, PAUL B. LAPHAM, in a field survey on NOVEMBER, 19 94,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law, established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1877 T. GALE MERRILL

SET POST

WIT.-BEECH 8" N72°E 05

HEMLOCK 8" N72°W 09

1982 MUELLER, L.C.R.C. #275

1983 LAPHAM, SURVEY

1983 LAPHAM, WORKSHEET

1989 WADE-TRIM-EDMAND, WORKSHEET

APPROVED LAND CORNER

P.A. 345 of 1990

Gladwin County

Co. Rep

Date

12-19-94

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND CAPPED IRON #25861, IN WOODED AREA. SEARCHED-FOUND NO OTHER CORNER EVIDENCE
15' EAST & 50± SOUTH OF 3 WAY WIRE.
N'LY 48.67' SPIKE IN 12" MAPLE
NE 25.69' SPIKE IN 5" MAPLE
S'LY 34.09' SPIKE IN 20" TWIN OAK
WSW 109.54' SPIKE IN 7" MAPLE IN CLUSTER
SET COR. FROM FOUND C.I. & WITNESSES OF RECORD.

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument.

Corner, K-3 was approved for remonumentation at a Peer Review Committee Meeting on 12-19, 1994.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-3: Corner common to Sections 1, 2, 11 & 12

SET 5/8" x 36" RE-ROD WITH GLADWIN COUNTY RE-MON CAP, MARKED P.S. #9433.

WITNESSES:

N10°E 12" MAPLE (SPIKE) 48.67'

N50°E 5" MAPLE (SPIKE) 25.69'

S10°W 20" TWIN OAK (SPIKE) 34.09'

N30°W 7" MAPLE (SPIKE) 109.54'



Signed by

Paul B. Lapham

Date

12-23-94

Surveyor's Michigan License No.

9433