BUHVEY & REMONUMENTATION

AUG 0 8 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office Cogebic County

Receiv	ed for record the
	ay of MAY
	at 1:55 o'clock
	, and recorded in
	d CORNER
Ramona Col	Lina Donuter
TONTIONATO	lin, Deputej

For corners in			13 TH day of MAY
Gogebic (County)	Located In:	Corner Code ##	A. D. 19 97 at 1:55 o'clock
1. Public Land Survey	T <u>45N</u> R <u>45W</u> T R T R T R	FG-5-6 # 002	Liber 6 of Convers m page 101 Ramone Collins, Deputin
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R		Register of Deeds Stamp & File Number
5. Private Claims	Recorded Plat		A B C D E F G H I J K L M
Richard L. Drah do hereby certify that under re- in lines 1 and 2 above were in current manual of survey instr Management or by a decree of above were in conformance with	IP in a field survey on <u>April</u> quirements of P.A. 74, Michigan P.A. n conformance with regulations a ructions of the United States Depa a Court of Law and/or that the corn ith the rules of the Michigan Board re-established, monumented, re-	. 28,	ned 6 18 17 16 15 14 3 3 14 5 4 15 14 5 4 15 14 5 5 1 14 5 15 14 5 15 14 5 15 14 5 15 15 15 15 15 15 15 15 15 15 15 15 1
NOTE: Not more than 4 con this certificate	corners, all in the same town a	nd range, may be recorded	11 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

Corner established by William Burt in 1847. Original B.T.s --- Hemlock 10" S.35 W. 14 links (9.2') --- 20" Hemlock N.55 E. 20 links (13.2') ---.

Corner restored by Earl Harrington in 1928 from the stump remains of the two original B.T.s. He set a standard State Line concrete, brass capped monument and established a new B.T.; Hemlock 12" S.66-15 W. 29.0 ft.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- Recovered the standard brass capped concrete monument as described in Earl Harringtons notes. His hemlock B.T. is now a hemlock stump decayed to below ground line.

No evidence remains of William Burts B.T. @ S.35 W. The original B.T. @ N.55 E. is now a series of large root holes, species undetermined.

Research Form on file with Gogebic County records.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the above described concrete monument I established the following new bearing objects:
 - 22.14 feet Yellow Birch N.47 W.
 - 20.05 feet 8" Red Maple N.69 E.
 - 4" Red Maple S.38 W. 21.40 feet
 - Steel sign rail N.05 E. 2.33 feet

MICH ٥Ŧ RICHARD L. DRAHN LAND SURVEYOR No.

April 29, 1997 Date __

Surveyor's Michigan License No. .

21564