SVEVEUS REMONSHEMMONER

DEC 1 5 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

densier	's Office - ounty	33.
1 stephic	•	
_	Received	for

For	comers	in	SECTION
For	comers	in	San Carl II I Wall !

GC	ngebic (County)	Located In:	Corner Code ##
1.	Public Land Survey	T 46N R 45W	A-1
		747N R45W	A-13
		T 46N R 46W	M-1
		T <u>47N R 46W</u>	M-13
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

A. B.	Received for record the 0" day of 0 c 70 BKA 19 9 B at 9:05 o'clock
k 116	m., and recorded in
Rom	ge 63 Grant Collyn, Deputy Register of Doods
	Register of Deeds

Register of Deeds Stamp & File Number


4.	Lot No.	, Recorded Plat
_		a

5. Private Claims _

Section Corner 6, 1, 31 & 36; T.46-47 N., R.45-46 W.

Richard I. Drahn, in a field survey on October 2, ..., 19 98..., do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:

Corner established by Austin Burt on 8/31/1847. Original B.T.s --- Y. Birch 18" S.34 E. 35 links (23.10') --- Cedar 12" N.66 W. 35 links (23.10') ---

R.G. Campbell, on 7/26/35 recovered both BT's still scribed and placed a location poster on the south side of a 16" Black Ash.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record bearing and distance from the remains of the two original BT's. The first one is a badly decayed 20-22" Yellow Birch stump. The second one is now a downed, badly decayed 14-18" Cedar with evidence of the GLO blaze overgrowth still present.

Campbell's tag tree is now a broken 20-24" Black Ash stub bearing N.72 W. 9.0' from the original corner location. Unable to find his location poster.

Corner research on file with Gogebic County records.

Richard A. Denha 10/27/98
COUNTE MATERIALIS

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position I set a 3/4" X 4' solid aluminum rod with a $3\frac{1}{4}$ " stamped aluminum cap and the following new bearing objects

9" Hemlock N.60 E. 15.35'
16" Hemlock N.13 E. 16.24'
6" Black Ash S.44 W. 20.55'
6' Steel sign rail S.79 W. 1.50'

A 3/4" iron pipe and two posts bears S.09 W., 12.9'

RICHARD
L. DRAHN
LAND
SURVEYOR
NO.
21564
LAND
LAND

Signed by Richard L. Wrahm

_ Date __October_6, 1998

Surveyor's Michigan License No. 21564

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983