REMONITOR STATION COMMISSION COrners in

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Register's Office ss.

For corners in Gogebic		Located In:	Corner Code =##			16				r rec				
	(County)	Locator III.	Corner Code -++		A.	D. 19			-	0:43				
1.	Public Land Survey	т <u>47N</u> R <u>47 W</u> Т В	A-B-1			A er				1000				
		T R	#001)		90	page.		68		•				
2.	Property Controlling in Section	S T R S T R			ÜΥ	NYK	YU			ter o				
3.		S T R S T R		Regis	ter	of De	eds		_					
4	Lot No , F	Recorded Plat				в с		E	<b>.</b>	в н	1 .	. 1 ж	, ,	14
5.					− j <del>e</del> -	ŤÌ	Ť	Ť	$\dot{\mathbf{T}}$	ĬÏ	<del>' '</del>	Ė		
	Meander corner common to Section 6, T47N, R47W and						5-		· • —	<u> </u>	+	ģ		-
	Section 31, T48N	, R47W.			3  -	++	+	+	+-	-	+	$\vdash$		
	John R. Garske	in a field survey on	December 7 10 94		<u>"</u>	7	8 	十	9-1	10- 	1-1	1 	-1	2
t, John R. Garske in a field survey on December 7 19 94 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned								╅						
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the						18	—17- 	1	16	15 	†	14— 		3
	current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5							_		$\sqcap$	1	$\vdash$		
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a						19-	—20- 	十	21	22-	1-2	₹3 	2 	4
Court of Law; established, re-established, monumented, re-monumented, recovered, found as						1 1		+	+		<del> </del>	T		
	pressed below:				ŀ	30	29- 	1	-28	27-	1-2	<i>≩</i> 6—⊣		5
ИО		orners, all in the same town a	ind range, may be recorded		'-	11		十	+ +		+	$\vdash$	H	
	on this certificate.			•	2	31-	-32-	+	33	3'4	-∤³	3 <sup>1</sup> 5	31	6
A	Description of original	monument and accessories an	nd/or subsequent restoration:	1	3	- <b>-</b>			4	<b></b>		1	<b></b>	

Original survey by William Ives, Deputy Surveyor, in 1848. Original corner was a cedar post and original bearing trees are: Hemlock 18" - N25°E, 28 links (18.48'); Hemlock 26" - S9°W, 34 links (22.44').

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence could be found. Corner position was re-established on the extension of the section line in conjunction with an ancient fence line west to the river's edge. The corner was placed at the top of bank so as to protect and preserve the integrity of the corner. This position matches G.L.O. call with measurement to the edge of the Montreal River.

Record research form on file with County Register of Deeds office. See sketch on back.

PEER GROUP Approved

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set a 2 1/2" x 30" aluminum monument with a 3 1/4" aluminum cap stamped: County Remonumentation; T48N, R47W, M.C.; S-31; S-6; T47; 1994; RLS 28410. Established the following bearing trees and reference object: 8" twin hemlock east, 27.03 feet; 8" sugar - S35°E, 50.14 feet; 5" sugar - S15°W, 13.05 feet; 6' steel rail with sign - N10°E, 2.36 feet.

Signed by

urvevor's Michigan License No.

28410

Date

12/15/948

LAND SURVEYOR No. 28410

OFMICA

John R. Garske

FORM APPROVED BY MICHIGAN STATE BOARD OF BOMB SURVEYORS, JAN. 28, 197

REVISED MAY 14, 1975 REVISED JAN., 1983

Fed. A-1-2

T47N, R47W

T48N, R47W