## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in			
Grand Traverse (County)	Located in:	Corner Code #	
1. Public Land Survey	T <u>27N_R_9W_</u> TR	<u>M-8</u>	
2. Property Controlling	S TR		
in Section 3. Miscellaneous	S TR		
Property in Sec.	S T R	·····	
,			Register of Deeds Stamp & File Number
4. Lot No, Reco	ded Plat		A B C D E F G H I J K L M
5. Private Claims			2 6 5 4 3 2 1
I, <u>Craig W. McVean</u> , in a field survey on <u>May 27</u> , 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree			3 4 7 8 9 10 11 12 5 5 6 18 17 16 15 14 13 7
	established, monumented, recovered,		9 10 30 29 26 27 26 25
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			11
A. Description of original monument and accessories and/or subsequent restoration:			
M-8 - 1850- GLO, L.Lyon, set Oak ¼ post N54°W 39 links 12" Yellow Pine, S°E 30 links 14" White Pine - M. Schaaf – 1934 +/- index shows corner found 1973- J.Wilcox, LCRC L.1, pg.172 Kal. Co. Rec Set 1" iron bar single proportion between fnd. corners North 28.59' to 15" Red Pine, N85°E 26.26' to 6" Red Pine S45°W 7.62' to 6" Jack Pine, N85°E 47.98' to 12" Red Pine			
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
M-8 – Standard ¼ corner common to section 24, T27N, R9W & section 19, T27N, R8W - Found 1" iron rebar in agreement with GLO 14" R. Pine stp. with hack marks to NW. Iron bar is 3' +/- E. of C/L of N-S fire lane just S. of diagonal NW-SE cross trail. Per discussion with R.F. Mitchell, he says that he had reset the record Wilcox iron bar after finding the GLO Pine stp. Says he was working for Wilcox at the time and that Wilcox & Associates would have documentation. Upon contacting Wilcox and Associates, they could not find this information. 1" Iron bar fits very close to midway between section corners N & S and based on GLO BT stump to NW it is accepted as a careful and faithful perpetuation of the position of the original corner Reference pt - Set 60D spike per Wilcox LCRC being S66°W 20.03' of M-8. Spike not utilized as M-8 in this survey.			
C. Description of monument t	or corner and accessories estab	lished to perpetuate locating the	position of the corner:
in a ring of stone – dov	vn 0.8'		n 2 ½ " X 30 " galvanized iron pipe
S86°W 13.18' to S75°E 30.57' to N39°E 23.78' to N30°E 34.93' to N66°W 37.18' to	ofnd. nail In N side 1 ofnd. nail in NE side 1 o set nail and tag in NW side ofnd. nail in SE side	4" Red Pine Stump (GLO) 6" Red Pine 3" Red Pine 12" White Pine scribed 'XBT' 12" Red Pine 22" White Pine scribed 'XBT'	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR
Set blue carsonite post with location tag 16.5' W.  Signed by			
Surveyor's Michigan License 1	vo. <u>39088</u>		- E8810A