

1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF LEELANAU
RECEIVED FOR RECORD

1993 DEC 28 PM 4: 27

For corners in

Leelanau
(County)

Located In:

Corner Code #

- | | | |
|------------------------------------|---------------------------|------------|
| 1. Public Land Survey | T <u>29N</u> R <u>11W</u> | <u>A-1</u> |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| | T _____ R _____ | _____ |
| 2. Property Controlling in Section | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |
| 3. Miscellaneous Property in Sec. | S _____ T _____ R _____ | _____ |
| | S _____ T _____ R _____ | _____ |

Barbara Kirt
REGISTER OF DEEDS

FILE #345

LIBER 2 PAGE 42

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Steven P. Bye, in a field survey on December 1, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-1: NW corner Section 6: G.L.O. "Set post and established corner of towns 29 & 30N, Ranges 11 & 12W"
Beech 9, N 44 W, 21 links
Do. 12, N 25 E, 20 links
Sugar 12, S 65 E, 45 links
Do. 16, S 78 W, 14 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-1: NW corner Section 6: 5/8" iron rod and cap #5942 found
5.6' West of E-W fenceline
4±' East of fenceline North

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-1: NW corner Section 6: 5/8" iron rod and cap #5942 accepted by the Leelanau County Remonumentation Peer Group, November 29, 1993, and replaced with a 3/4" i.d. galvanized iron pipe 3' long with a brass cap.

12" maple - S 51 W, 20.59' found spike
16" maple - S 85 E, 20.97' found spike
10" maple - N 10 W, 23.29' found spike
8" maple - S 15 W, 15.95' set spike

Signed by Steven P. Bye

Date 12-20-93

Surveyor's Michigan License No. 35991

