

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 51N R 36W	C8
	T R	
	T R	
2. Property Controlling in Section	S T 51N R 36W	8
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8	19		20		21		22		23		24		
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 8 05/01/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(C8) Quarter corner common to Sections 19 and 20. 1992 - Reestablished by the undersigned midway and
on the Section line between Section corners 2547.24' north and south. Set 1"IDx32" I.pipe with 4"
alum. MDNR cap. 18" Basswood S39W 5.8', 4" Balsam N05W 28.8', 12" Y.Birch N57E 24.3', 3" Maple S79E
7.9'

(8-Sec. 19) West 1/16 corner, Section 19. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(C8) Found the 1992 monument in good condition and at record bearing and distance from the Basswood,
Y.Birch, and Maple NBTs, all in good condition. Made new witnesses as described below. The Balsam
NBT was not recovered.

(8-Sec. 19) Established the position for the corner on a straight line between Quarter corner
1310.31' west and Center of Section 19 1316.24' east, the position being 20.00 chains, proportionate
to the original US record, west of the Center of Section.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(C8) Fd. 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
17" Basswood S42W 6.8' scribe visible 1992 NBT
13" Y.Birch N58E 24.65' do do
4" Maple S78E 8.15' do do
3" Oak N34W 16.5' mrkd "1/4S NBT"
Set sq'd cedar post adjacent.
Bearings are magnetic.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" dbl Maple N08W 15.0' mrkd "1/16S BT"
6" Maple N47E 10.5' do
14" W.Pine S32W 24.05' do
10" Spruce N74W 17.1' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 05/08/2012

For the Michigan Department of Natural Resources, Forest Resources Division

