

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 27 T 51N R 36W S 27 T 51N R 36W S _____ T _____ R _____ S _____ T _____ R _____	12 8 _____ _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

12 06/11/2008

I, Stephan J. Szyszkoski, in a field survey on 8 06/11/2008 do hereby state

that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(12-Sec. 27) South 1/16 corner, Section 27. Not established in the original survey.

(8-Sec. 27) West 1/16 corner, Section 27. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(12-Sec. 27) Established the corner midway and on a straight line between Quarter corner 1360.42' south and Center of Section 27 1360.42' north. From the position thus established, I found a bent 1.5" ID Iron pipe, not of record, S37W 53.3' distant, which I did not accept as marking the position for the corner.

(8-Sec. 27) Established the corner midway and on a straight line between Quarter corner 1325.45' west and Center of Section 27 1325.45' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" twin Sugar N57E 14.1' mrkd "1/16S BT"
7" Sugar S80E 3.5' do
4" Sugar S03E 10.25' do
5" Sugar N63W 6.9' do
Set sq'd cedar post adjacent. Bearings magnetic.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Maple N75E 23.3' mrkd "1/16S BT"
5" Sugar S19W 6.6' do
7" Maple N63W 22.5' do
6" Sugar N31W 12.7' do
Set sq'd cedar post adjacent. Bearings magnetic.

Signed by

Stephan J. Szyszkoski

Date

08/11/2008

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities



16099

16100

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 10, 1971
Revised May 14, 1975
Revised Jan., 1983
Revised Oct., 1995