

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| | | |
|---------------------------------------|------------------|---------------|
| Houghton (County) | Located In: | Corner Code # |
| 1. Public Land Survey | T 52N R 35W | E13 |
| | T | |
| | T | |
| 2. Property Controlling in Section | S T | |
| | S 33 T 52N R 35W | 10 |
| | S T | |
| 3. Miscellaneous Property in Sec. | S T | |
| | S T | |
| 4. Lot No. _____, Recorded Plat _____ | | |
| 5. Private Claims _____ | | |

I, Stephan J. Szyszkoski, in a field survey on E13 01/18/2012
10 01/18/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(E13) Section corner common to Sections 32-33 T52N-R35W and Sections 4-5 T51N-R35W. 1953 - The
original corner position was remonumented by D.C.DeLaMater RLS from two original B.T.s still in
place, one in excellent condition, one fair. Set 1" pipe with 4" brass cap. 20" H.Maple East 32
links, 8" H.Maple S45W 40 links.

(10-Sec. 33) South 1/16 corner between Sections 32 and 33. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(E13) Found the 1953 monument in good condition and at record bearing and distance from the 1953
witness Sugar S45W 40 links, in good condition with overgrown blazes. Accepted the monument as a
careful and faithful perpetuation of the position of the original corner.

(10-Sec. 33) Established the position for the corner midway and on the Section line between Section
corner 1278.70' south and Quarter corner 1278.70' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(E13) Found 1"ID I.pipe with 4" brass MI Dept.
of Conservation cap.
Set measuring nail with MDNR tag in the side of:
15" Sugar S48W 26.5' old blazes 1953 NBT
12" Sugar N18W 4.7' mrkd "S32 NBT"
4" Sugar N77E 7.35' "S33 NBT"
4" Sugar S19W 14.65' "S5 NBT"
Set sq'd Cedar post adjacent.
Bearings are magnetic.

(10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Y.Birch N13W 22.7' mrkd "1/16S BT"
4" Sugar N60E 33.0' do
8" Y.Birch S25E 9.55' do
7" Sugar S39W 11.35' do
Set sq'd Cedar post adjacent.
Bearings are magnetic.

Register of Deeds Stamp & File Number

| 1 | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|----|----|----|----|----|----|---|---|---|---|---|---|---|
| 2 | 5 | 5 | 4 | 3 | 2 | 1 | | | | | | | |
| 3 | | | | | | | | | | | | | |
| 4 | 7 | 8 | 9 | 10 | 11 | 12 | | | | | | | |
| 5 | | | | | | | | | | | | | |
| 6 | 18 | 17 | 16 | 15 | 14 | 13 | | | | | | | |
| 7 | | | | | | | | | | | | | |
| 8 | 19 | 20 | 21 | 22 | 23 | 24 | | | | | | | |
| 9 | | | | | | | | | | | | | |
| 10 | 30 | 29 | 28 | 27 | 26 | 25 | | | | | | | |
| 11 | | | | | | | | | | | | | |
| 12 | 31 | 32 | 33 | 34 | 35 | 36 | | | | | | | |
| 13 | | | | | | | | | | | | | |

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 01/31/2012

For the Michigan Department of Natural Resources, Forest Resources Division

