

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 35W	M7
	T R	
	T R	
2. Property Controlling in Section	S 14 T 52N R 35W	3
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 3 08/05/2010 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M7) Corner common to Sections 13-24 T52N-R35W and Sections 18-19 T52N-R34W. 1972 - A.O.Enger RLS reestablished the corner in the approximate centerline of N & S road, 50 links W. of a N & S fence line parallel to the road and in line with a fence going E. and one going W., which is accepted as the corner by common report. Set 1"IDx36" I.pipe with 4" alum. cap. Red Maple 8" S63W 116.1', R.Maple 6" N72W 69.2', W.Spruce 12" S81 1/2E 56.7'.

(3-Sec. 14) North 1/16 corner between Sections 14 and 15. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M7) Found the 1972 monument in good condition at record bearing and distance from the W.Spruce NBT SE, found in good condition with overgrown blazes. Accepted the monument as the best available evidence of the position of the original corner.

(3-Sec. 14) Established the corner midway and on the Section line between Quarter corner of record 1271.05' south and Section corner of record 1271.05' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M7) Found 1"ID I.pipe with 4" alum. MI Dept of Conservation cap.  
Set measuring nail with MDNR tag in the side of:  
14" W.Spruce S79E 56.95' old marks (1972 NBT)  
6" W.Spruce S31E 18.4' mrkd "S19 NBT"  
7" Maple N64W 29.35' "S13 NBT"  
7" W.Spruce N77E 18.85' "S18 NBT"  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
9" Maple N02W 25.3' mrkd "1/16S BT"  
9" Y.Birch S80E 7.75' do  
19" Hemlock S17E 27.7' do  
13" Hemlock S72W 12.65' do  
Set sq'd cedar post adjacent.  
Bearings are magnetic.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 10/20/2010

For the Michigan Department of Natural Resources and Environment, Forest Management Division

