

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 35W	A3
	T 52N R 35W	B3
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File
Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

Jun 13 2007

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A3) Corner common to Sections 6-7 T52N-R35W and Sections 1-12 T52N-R36W. 1840 - Established by Wm.A.Burt Deputy Surveyor. Set post. Spruce 7 S68E 19 links, Tamarack 8 N8W 23 links.
(B3) Quarter corner common to Sections 6 and 7. 1957 - Remonumented by Billy D. Buckler RLS, in the original position from one Sugar B.T. N55W 60 links, dead but in fair condition. Set 1" pipe with 4" brass cap. 8" Hard Maple S14W 32 links, 8" Hard Maple squared and scribed at corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A3) The original post and accessories were not recovered. Found a 1" ID I.pipe, not of record, origin unknown, which is located 12.4' west and 4.1' south of the proportionate position for this corner based on the GLO record between monumented corners at A1 and A7. Accepted the monument as the best available evidence of the position of the original corner.
(B3) Found the 1957 monument in good condition and at record bearing and distance from the stump hole remains of the 1957 Sugar NBT SW and with the the squared and scribed Sugar adjacent, found in good condition with overgrown blazes. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A3) Found 1" ID I.pipe w/ mushroomed top projecting 6" above ground. Set measuring nails in: 5" B.Spruce N40W 16.1' mrkd "S1 NBT" 7" B.Spruce N19W 2.55' do 9" Tamarack S40E 53.4' "S7 NBT" 4" W.Pine S74W 24.25' "S12 NBT" Set sq'd cedar post adjacent. Bearings are magnetic. Distances are to nail with MDNR tag.	(B3) Found 1" ID I.pipe with 4" brass MI Dept. of Conservation cap. Set measuring nails in: 13" Sugar S47E 1.55' old blazes 8" Sugar S48W 19.9' mrkd "1/4S NBT" 8" Sugar N44E 9.7' do 8" Sugar N86E 12.5' do Bearings are magnetic. Distances are to nail with MDNR tag.
---	---



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 7/12/07

For the Michigan Department of Natural Resources, Office of Land and Facilities