

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 20 T 52N R 36W S _____ T _____ R _____ S 20 T 52N R 36W	16 (GCDB 260300) 15 (GCDB 220300)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4			3		2	1
3													
4	7			8			9			10		11	12
5													
6	18			17			16			15		14	13
7													
8	19			20			21			22		23	24
9													
10	30			29			28			27		26	25
11													
12	31			32			33			34		35	36
13													

I, Stephan J. Szyszkoski, in a field survey on 10/28/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(16-Sec. 20) East 1/16 corner between Sections 20 and 29. Not monumented in the original survey.

(15-Sec. 20) West 1/16 corner between Sections 20 and 29. Not monumented in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(16-Sec. 20) Found a 1.5"ID iron pipe, projecting 18" above ground, the same type of monument found elsewhere throughout this township and possibly established by mining company surveyors long ago, 0.99' west and 0.56' south of the record position for this 1/16 corner. I accept the pipe as a careful and faithful establishment of the position of the corner.

(16-Sec. 20) Found a 1.5"ID iron pipe, projecting 12" above ground, the same type of monument found elsewhere throughout this township and possibly established by mining company surveyors long ago, 1.75' west and 0.37' north of the record position for this 1/16 corner. I accept the pipe as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(16) Found 1.5" ID iron pipe.  
Set measuring nail with MDNR tag in the side of:  
6" Ironwood N42°E 12.0' mrkd "1/16S BT"  
9" Basswood S51°E 19.8' do  
18" Oak S15°W 17.85' do  
18" Sugar N78°W 12.3' do  
Set sq'd sugar post adjacent.  
E= 7855562.360 N= 234800.347

(15) Found 1.5" ID iron pipe.  
Set measuring nail with MDNR tag in the side of:  
6" Oak N18°E 31.95' mrkd "1/16S BT"  
8" Maple N83°E 12.5' do  
4" Sugar S27°E 17.6' do  
7" Maple S67°W 10.1' do  
Set sq'd cedar post adjacent.  
E= 7854734.893 N= 234789.503

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).  
Coord. Ref.=NGS PID RL0502: N= 234995.272 m. E= 7857774.766 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 11/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

