

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 36W	K10
	T R	
	T R	
2. Property Controlling in Section	S 25 T 52N R 36W	3
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 05/23/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(K10) Quarter corner common to Sections 25 and 26. 1846 - Established by Sylvester Higgins and
Hiram Higgins, Deputy Surveyors, midway and on the Section line between Section corners 40.00 chains
north and south. Set post. Y.Birch 14" N35E 28 links, Sugar 8" S70W 13 links.

(3-Sec. 25) North 1/16 corner between Sections 25 and 26. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(K10) The original post and accessories were not recovered. The mile K9 to K11 is 5.17 chains
shorter than the original record between monumented Section corners. At a position 122.76' South
and 16.76' East of the proportionate position, I found a 1 3/4" ID iron pipe, set firmly, projecting
19" a.g., similar in type to other old pipes previously found in this township, those pipes known to
have been set many years ago, mostly by mining companies. I accept the pipe as the best available
evidence of the position of the corner.

(3-Sec. 25) Established the position for the corner midway and on the Section line between Section
corner 1296.07' north and Quarter corner 1296.07' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(K10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap
inside found 1 3/4" ID iron pipe.
Set measuring nail with MDNR tag in the side of:
12" Hemlock N10W 17.65' mrkd "1/4S NBT"
9" Sugar N39E 8.5' do
8" Maple S14E 30.7' do
9" Maple N81W 7.9' do
Set sq'd cedar post adjacent.
E= 7860853.193 N= 233779.703

(3) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Maple N28E 16.7' mrkd "1/16S BT"
9" Y.Birch S03W 6.75' do
5" Spruce N60W 7.4' do
13" Hemlock N22W 18.2' do
Set sq'd cedar post adjacent.
E= 7860865.417 N= 234174.525

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)
Coord. Ref.=NGS PID RL0503: N= 233736.671 m. E= 7856830.966 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/30/2013

For the Michigan Department of Natural Resources, Forest Resources Division

