

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 36W	M10
	T R	
	T R	
2. Property Controlling in Section	S 25 T 52N R 36W	14
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Stephan J. Szyszkoski, in a field survey on 14 03/08/2012 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(M10) Quarter corner common to Section 25 T52N-R36W and Section 30 T52N-R35W. 1963 - Remonumented by
Billy D. Buckler RLS as the position of an old down post and from B.T. Sugar 14" N73E 16 links. Set
1"ID I.pipe with 4" brass cap. 14" Hemlock N65W 41 links, 9" Hemlock S12E 26 links.

(14-Sec. 25) South 1/16 corner between Section 25 T52N-R36W and Section 30 T52N-R35W. Not previously
monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(M10) Found the 1963 monument as described, in good condition and at record bearing and distance from
the 1963 witnesses. The Hemlock NBT SE is in good condition with overgrown blazes. The Hemlock NBT
NW is a dead stub with scribing visible. Accepted the monument as a careful and faithful
perpetuation of the position of the original corner.

(14-Sec. 25) Established the position for the corner midway and on the Range line between Section
corner 1324.57' south and Quarter corner 1324.57' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(M10) Fd. 1"ID I.pipe with 4" brass MI Dept.
of Conservation cap.
Set measuring nail with MDNR tag in the side of:
12" Hemlock S09E 17.7' old blazes 1963 NBT
7" Sugar N33E 27.85' mrkd "1/4S NBT"
4" Sugar N64E 14.95' do
8" Sugar S83W 8.15' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(14) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" Sugar N18E 24.9' mrkd "1/16S BT"
12" Maple N70E 6.7' do
7" Y.Birch S14E 16.0' do
13" Sugar S53W 8.85' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/26/2012

For the Michigan Department of Natural Resources, Forest Resources Division

