

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Houghton

(County)

Located In:

Corner Code #

1. Public Land Survey

T 52N	R 36W	F9
T 52N	R 36W	E8
T	R	
T	R	
S	T	R
S	T	R
S	T	R
S	T	R

2. Property Controlling
in Section

3. Miscellaneous
Property in Sec.

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

E8 Jun 20 2002
F9 Jun 19 2002

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(F9) Quarter corner common to Sections 21-28. 1846: Established by Sylvester W. Higgins: "West corrected...39.98 Set 1/4 Sec. post. Ironwood 8 N40W 24, Sugar 15 S35E 9...79.97 Sec corner". Found no subsequent record.

(E8) Quarter corner common to Sections 20-21. 1846: Established by Sylvester W. Higgins: "North...40.00 Set 1/4 Sec post...B.Ash 10 N85E 15, Sugar 8 S20W 19...80.00 Set post cor Sec 16,17,20,21". Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F9) The original post and accessories were not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner on a line of Mean True bearing between section corners 2682.63' east and 2683.32' west, being proportionate to the original record. The Mean True bearing of this section line is N86 deg. 07'E.

(E8) The original post and accessories were not recovered. Found no acceptable evidence of the position of the corner on the ground. Reestablished the corner midway and on a line of Mean True Bearing between Section Corners 2512.30' north and south, being the proportionate position. The Mean True bearing of this section line is N0 deg. 04'E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F9) Set 1"IDx32" I.pipe with 4" alum.

MDNR cap. Blazed and scribed:

8" Sugar N21E 15.3' "1/4S NBT"

14" Sugar S74E 17.1' do

8" Sugar S24W 30.4' do

8" Sugar N42W 14.4' do

Set a sq'd sugar post adjacent.

Bearings are magnetic. Distances are to notch in lower blaze.

(E8) Set 1"IDx32" I.pipe with 4" alum.

MDNR cap. Blazed and scribed:

10" N'ly Basswood S85E 1.0' "1/4S NBT"

9" Basswood S01W 12.3' do

7" Sugar S48W 29.8' do

11" B.Ash N35W 17.4' do

Bearings are magnetic. Distances are to notch in lower blaze.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 7/17/02

For the Michigan Department of Natural Resources - Office of Property Management

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1985