

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Houghton

(County)

Located in:

Corner Code #

1. Public Land Survey

T 53N R 34W A4
T R
T R
T R
T R

2. Property Controlling
in Section

S 7 T 53N R 34W 12
S T R
S T R
S T R

3. Miscellaneous
Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

Jul 16 2003

I, Stephan J. Szyszkoski, in a field survey on , 20 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

(A4) Quarter corner between Sections 7 T53N-R34W and 12 T53N-R35W. 1961: Remonumented and recorded by Billy D. Buckler at the location of a found wood post and 3/4" iron rod, with possible 08T Birch S22W standing and possible 08T Sugar stump hole. Set 1" pipe with 4" brass cap. 10" Y. Birch N13E 55.5 links, 16" H.Maple S13E 34 links.
(12-Sec. 7) South 1/16 corner, Section 7. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(A4) Found the 1961 monument in good condition and at record bearing and distance from the 1961 Sugar, in good condition with blazes overgrown, and the 1961 Y.Birch, down. Left the monument in place and made new witnesses as described below.
(12-Sec. 7) Established the corner midway and on a straight line between Center of Section 1316.42' north and Quarter corner 1316.42' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(A4) Found 1" ID I.pipe with 4" brass MI Dept. of Conservation cap. Blazed, scribed, and set meas. nails in:	(12) Set 1" IDx32" I.pipe with 4" alum. MDNR cap. Blazed, scribed, and set measuring nails in:
18" Sugar S11E 22.5' the 1961 NBT	5" Sugar S06E 6.5' "1/16S BT"
5" Sugar S06W 13.4' "1/4S NBT"	4" Sugar S57W 24.9' do
4" Sugar N51E 16.3' do	5" Y.Birch N60W 21.9' do
11" Hemlock S74E 26.7' do	4" Sugar N01W 15.9' do
Set a sq'd Maple post adjacent.	Set a sq'd Sugar post adjacent.
Bearings are magnetic. Distances are to nail with tag.	Bearings are magnetic. Distances are to nail with tag.



Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 7/23/03

For the Michigan Department of Natural Resources - Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1985