JUL 2 3 1999

SECTION

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995

## APPROVED LAND CORNER P.A. 345 OF 1990 Houghton County

Surveyor's Michigan License No.

By: Hitch, Inc., P.C., Houghton, MI

Job No. 97012

For corners in

Bohl W. Couple

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Ho	ughton County (County)	Located In:	Corner Code #		05/05/99 NTY, REGISTER 1:	2 5:04		
1. Pu	ıblic Land Survey Se	T R T R	(Meander Corner)	LC 3/589	Page 1 of	9.00 1		
in 3. M	operty Controlling Section iscellaneous	TR ST_R ST_R	•	-	Register of De	eds Stamp (	s Flie	
	Property in Sec. S I R Number							
4. La 5. Pr	it No, Redivate Claims	corded Plat				FGHI		
	orner A, B-3 is the me ommon to Section 6 &		re of Portage Lake, on section	2	6 5 5	4 3	J K L 1	
state 1 and manu: Mana; 5 abo	that under requirements 2 above were in confor al of survey instruction gement or by a decree of we were in conformance	of P.A. 74, Michigan P.A. of 1 rmance with regulations and r is of the United States Department of Law and for that the with the rules of the Michigan	December 23 , 19 97 of 1970, the corner points mentionerules therefore as required in the artment of the Interior, Bureau accorner points mentioned in lines a Board of Land Surveyors or by , recovered, found as expressed	ed in lines e current of Land s 3, 4 and a Decree	19 17 1	9 10 6 15 2	11 12	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.				ed \(\bigg\)	30 29 2	8 27	26-25-	
A E	Description of original	monument and accessories	s and/or subsequent restoration	on:	31 -32 -3	334	35 36	
Meander Corner - At 47.24 chains (from the NE corner Section 7), intersect north arm of Portage Lake.					Corner A, Meander Co			
		Meander Corner – Spruce 8 uce 6, S65E, O4	8	<sup>North</sup> Comment	12011111	**************************************		
	lo evidence of original July 5, 1845 and July		found. This line was origina	lly surveyed by D	Peputy Surveyo	r William Ive	s between	
8. C	escription of corner e	vidence found and/or meth	od applied in restoring or ree	stablishing corner	r:			
r	etracing Helmuth's su	irvey I did not find any iron	M. Steinhilb, RLS 8896 show pipe along the shore of Porta Helmuth, using the found no	age Lake on the s	ection line. Th	is meander d	corner was	
C. D	Description of monument for corner and accessories established to perpetuate locating the position of the corner:							
A	Il witness points in t	trees are PK nails and wa	shers.					
M	leander Corner - Se	t ½″ iron.	CE OF I	MICHELL				
<u>W</u>	(itnesses:		ESS AND					
N S S	58° E, 30.09 ft., 22° E, 55.63 ft., 23° W, 28.05 ft., 60° W, 28.12 ft.,	, 16″ Maple , 7″ Spruce	Land St	YS YOR Coto				
Signe	d by MUMUS	M. Mu	yu min	Date	April 13, 1	999		