APPROVED LAND CORNER P.A. 345 OF 1990

Roll W. Camps

SEP 1.7 1999

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners in	•	• • • • • • • • • • • • • • • • • • • •	
Houghton	Located In:	Corner Code # NAMES	feet from L. a. w. a
(County)			FENILI 12/11/97
			ON COUNTY 11:22
1. Public Land Survey	T55N R 32W	₂₁ /1) LC	3/ 450 PAU Fee: 11.00
1. I donc Land Survey		27-1	Page 1 of 2
	T55N R 32W		
	<u>T</u> R		
	、Τ R		\$
2. Property Controlling	ST R		
in Section	S T R		
3. Miscellaneous	S T R		
Property in Section	ST R		Register of Deeds Stamp & File Number
• •		<u> </u>	
4. 1 ot No	Recorded Plat		•
5 Private Claims			A B C D E F G H I J K L M
b. Trivate Olamis			2 - 6 - 4 - 1 - 3 - 1 - 2 - 1
	•		
			4 7 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -
	ja a field survey on Octobe		. 5
	quirements of P.A. 74, Michigan P.A. of		
·	conformance with regulations and rules		
	is of the United States Department if a Court of Law and/or that the comer		
	e with the rules of the Michigan Board		
	ablished, re-established, monumented,		
as expressed below:	ibilition, to obtaining, moritamentos,	To moralitation, reported as, realita	10 30 29 28 27 26 25
•			11
on this certificate.	orners, all in the same town and ran	ige, may be recorded	12 31 32 33 34 35 35
on this oer mode.		-	12 3 33 33 33 33 33
A Description of original	monument and accessories and/	or subsequent restorations	[Q
•		•	F - 1 6
	Z1) Meander Corner		
	tersected Lake at mo		
N.N.W. S	et Meander Post I	White Pine 12" N22	/ዐር //5 1ሎ/

Meander Corner between Sections 8 and 17

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Do 10 S10°W 07.

Corner Code (21) Meander Corner between Sections 5 and 6
No evidence of original post found Set 1/2" rebar
with 1/2" pipe over rebar at record GLO distance from
NW Corner Section 5.

51.44 Intersected Lake Cedar 8 for Meander Corner

Corner Code (Z7) Meander Corner between Sections 8 and 17 No evidence of original corner found Set 1-1/2" pipe for meander corner along Section line 713.98' from 1/4 corner 22'+ from water's edge.



- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - Corner Code (Z1) Meander Corner between Sections 5 and 6
 Cemented brass remonumentation cap into pipe and stamped MC
 References: 9" White Birch N84°E 29.6', SW Cor. 9th St. 6 5
 Substation Workshop (Brick) N11°E 212.80', SE Cor. 1997
 Torch Lake Sewage Authority bldg.(Metal) N16°W 142.27' T55N-R32W
 See back.
 - Corner Code (Z7) Meander Corner between Sections 8 and 17
 Cemented brass remonumentation cap into pipe and stamped MC
 References: 12" Spruce w/ tag# 39478 N17°W 6.95', 8" | 8
 Maple w/ tag# 39478 S66°E 47.34', 3/4" pipe with cap# | 17 1997
 19833 S02°E 66.32', 3/4" pipe w/cap# 19833 N28°E 89.03'.T55N-R32W

	19833 SUZUE 66.34", 3/4"	bibe M/cab# 18833 MS8 R 88.03. 123M-	RJZW
Signed by	Konold & Hostoia	pipe w/cap# 19833 N28 89.03 . 155N- Date <u>November 25, 1997</u>	