Houghton country A
Rolet W. Compo
John W. Warry
Oct 18 1999
- Land Contract Contr

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

JAN 2 5 2000

3

8

9

10

11 12

13

32

For comers in

Houghton County Located in: SECTION Comer Code # 1. Public Land Survey T55N R33W G - 5Mary Schoos 1 🖺 Т R Register of Deeds T R Houghton County, Register T R Page 1 of 1 LC 4/47 2. Property Controlling S Т R PAU Date 12/30/1999 Time 10:33:59 in Section S 7 R CCC. 9. 00 Miscellaneous S T R Property in Sec. S Register of Deeds Stamp & File Number

4 Lot No.

, Recorded Plat

**Private Claims** 

I, Joseph C. Domitrovich, in a field survey on October 21, 1999, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
  - (G 5) Corner Common to Sections 9, 10, 15 & 16, T55N, R33W.
  - 1846 L.S. Scranton set a post with ties:

15" Sugar S 18°W 42 links 14" Sugar N 30°E 20 links

- 1910 D.W. Holland calls for a 1 1/4" iron pin set in concrete at this corner. Calculations from his field notes show a distance east to the N 1/4 Comer, Sec. 15. (Notes on file with Lake Superior Land Co. of Calumet).
- 1918 H.W. Fesing, Engineer, in his field notes (Book 38 on file with Steve Hein, P.S., of Laurium) shows this corner and distances to corners to East and South. He does not indicate what the corner is.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I found no remains of the original corner or accessories. I found a ½" iron pin with cap #24625, re-established by Duane Wood, P.S., as part of the Houghton County Airport survey. This comer now falls in the cleared area for Airport Runways. It falls on the extension of County Roads to the North, East and West. Distances from this corner to the corners East and South work well with Fesing and Holland's.

> N 1/4 Corner Section 15 2694.26' (m) N 88°45'31"E (2697.6' Fesing) (2694.95' Holland) W 1/4 Corner Section 15 2652.52' (m) S 00°05'14"E (2649.2' Fesing) N 1/4 Corner Section 16 S 89°02'31"W 2621.94' (m)

I accepted this iron pin as the section corner and placed a 3/2" pipe and cap over it.

C. Description of monument for comer and accessories established to perpetuate locating the position of the corner:

Corner is a 3/4" iron pipe with a brass "Houghton County Remonumentation" cap. Ties:

Centerline Runway 13/31 S 39°43'W 190.3 (Meas. @ rt. Angle to Runway) Centerline Runway 7/25 24°16'E S 1158.6' (Meas. @ rt. Angle to Runway)

P.K. @ Intersection of Centerlines S 41°15'05"E 1211.52 NE End of Runway 7/25 Monument S 88°21'14"E 2650 63 No other ties available.

NOTE: Bearings to witness objects are magnetic. Distances are to a nail in side of the witness object unless noted.

Date

Surveyor's Michigan License No. 37273

OF BICHIO TOSEPH DOMITROVICH

25

REVISED OCT., 19

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SUI