

JAN 19 2001

SECTION

2000 REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in CASEVILLE Township

Huron  
(County)

Located in:

Corner Code #

1. Public Land Survey T 18N R 10E L - 13  
T — R —  
T — R —  
T — R —  
2. Property Controlling S T — R —  
in Section S T — R —  
3. Miscellaneous S T — R —  
Property in Sec. S T — R —

STATE OF MICHIGAN  
HURON COUNTY  
RECORDED

8 DEC 2000 9:56 AM

FRANCES L. HOLDWICK  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Russell L. Brown, in a field survey on October 3, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4, and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2	8		5		4		3		2		1		
3													
4	7		6		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

1835, GLO H. Parke D.S. Set quarter Section Post  
Sugar 24 N83 1/2E 45; Beech 17 N61 1/2W 42  
COUNTY SURVEYOR RECORD: None  
COUNTY ROAD COMMISSION RECORD: None  
L.C.R.C.: None  
RECORDED SURVEYS: None  
UNRECORDED SURVEYS: None  
RECORDED PLATS: None

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner or accessories found.

Set 1/2" x 18" Steel Stake capped 24588 by single proportionate measurement between M-13 and K-13, T18N-R10E as best evidence of original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L - 13, S. 1/4 Corner Section 36, T18N-R10E  
Set 1/2" x 18" Steel Stake (Re-Rod) capped 24588  
WITNESSES:  
S70°E 199.70' to Nail & Bottle Cap in North Side Power Pole  
S60°W 25.10' to 1/2" x 18" Steel Stake (Re-Rod) set  
N55°W 23.59' to 1/2" x 18" Steel Stake (Re-Rod) set  
N60°E 26.38' to 1/2" x 18" Steel Stake (Re-Rod) set  
East 2613.13' to M-13, S.E. Cor. Sec. 36, T18N-R10E  
West 2613.13' to K-13, S.W. Cor. Sec. 36, T18N-R10E

Signed by Russell L. Brown  
Surveyor's Michigan License No. 24588

Date Nov. 2, 2000

Peer group approved at meeting held November 2, 2000. RLB

