

# LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

Re-Mon. Liber 2, Page 5

For Corners in

Huron  
(County)

Located in:

Corner Code #

1. Public Land survey: Lake

T 18\_N\_ R 11\_E

B-13 ✓

T R

C-13

T R

T R

2. Property Controlling  
in Section

S T R

S T R

3. Miscellaneous  
Property in Sec.

S T R

S T R

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_

5. Private Claims \_\_\_\_\_

SECTION

I, James T. Meek, in a field survey on October 30, 1999

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original survey, South Bdy. T18NR11E, 1835,  
Harvey Parke D.S.

B-13 South ¼ Corner of Section 31  
Post  
Elm 26", N55½°W, 17 links  
Lynn 12", N70°E, 19 links

County Surveyor's Record: none  
Recorded Surveys: none  
LCRC: none

C-13 Corner of Sections 31 and 32  
Post  
Cedar 11", N82°E, 14½ links  
Cedar 8", N56°W, 3 chains

County Surveyor's Record: none  
Recorded Surveys: L5, P232  
LCRC: none

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-13 South ¼ Corner of Section 31

Found ¾" iron in mon box

Accepted as the best available evidence  
of the original corner position.

C-13 Corner of Sections 31 and 32

Found no evidence of the original corner  
position

Set ½" iron w/cap #39089 in mon box based  
on Liber 5, Page 232, Huron County Records

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-13 South ¼ Corner of Section 31

¾" iron in mon box

From which:

Do Not Pass sign post bears N10°W, 19.5'

½" iron bears N45°E, 33.0'

No Passing Zone sign post bears S10°W, 19.4'

½" iron bears S45°W, 26.0'

C-13 Corner of Sections 31 and 32

½" iron w/cap #39089 in mon box

From which:

¾" iron in mon box bears East, 52.14'

West leg direct. sign bears N45°E, 61.8'

Tag in PP bears S35°E, 43.2'

½" iron bears N70°W, 42.0'

Signed by

Date

12-21-99

Surveyor's Michigan License No. 39089APPROVED AT PEER BOARD MEETING 12-16-99 RLB

RECORDED

DEC 28 4 18 PM '99

Francis McLaughlin

REGISTER OF DEEDS  
HURON COUNTY, MICHIGAN

Register of Deeds Stamp &amp; File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													