



HILLSDALE COUNTY REMONUMATION PROGRAM
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 3 PAGE 307

021811

RECORDED
HILLSDALE CO. MICH.

99 AUG 23 PM 4:00

Jeffrey VanZandt
REG. OF DEEDS

Register of Deeds Stamp & File Number

For corners in

HILLSDALE COUNTY

Located In:

Corner Code #

FAYETTE TWP

1. Public Land Survey

T 5 S R 3 W

G-12

T R

T R

T R

2. Property Controlling
in Section

S

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

I, EDWARD W. REED, in a field survey on JUNE 18, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

QUARTER CORNER COMMON TO SECTIONS 33 & 34

A. Description of original monument and accessories and/or subsequent restoration:

1825: GLO CORNER SET

1971: A.J. HATT, SURVEYOR, CORNER STONE RECORDED AS REMOVED BY ROAD

GRADING BY E.G. FITTS, R.P.E., OCTOBER, 1953, IN SURVEY FOR GEORGE

BROWN, AND REPORTED AS BEING AT THE CENTERLINE OF EXISTING ROAD IN LINE WITH FENCES EAST AND WEST AT A DISTANCE 2639.89' EAST OF THE CENTER POST OF SECTION 33, SET RR SPIKE AT PLACE NOTED, LCRC RECORDED IN LIBER 1, PAGE 29

1988: RUSSELL L. ROON, SURVEYOR, FOUND 3/8" IRON ON CENTERLINE AT ROAD SURFACE A DISTANCE OF 2635.71' FROM SOUTHEAST CORNER, SECTION 33, FITTING WITNESSES OF HATT

1998: JOHN E. MAXSON, SURVEYOR, SURVEY TIED TO CORNER

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND IRON FITTING WITNESSES OF ROON

REMOVED IRON AND SET 3/4" IRON WITH REMON CAP IN CAST IRON MONUMENT BOX

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" IRON WITH REMON CAP SET IN CAST IRON MONUMENT BOX

WEST 27.83' - EAST FACE OF FENCE POST

S 60 E 39.12' - NAIL AND CAP NORTH SIDE 40" OAK

N 35 E 67.45' - NAIL AND CAP NW SIDE 36" HICKORY

N 45 W 39.4' - TOP OF TELEPHONE PEDESTAL

N 18 W 71.25' - 36" HICKORY

N 85 E 29.95' - NAIL AND CAP NORTH SIDE OF 34" OAK

N 40 E 36.8' - NAIL AND CAP WEST SIDE OF 34" WALNUT

S 32 W - 61.23' - NAIL AND CAP EAST SIDE TRIPLE POPLAR

N 32 W 59.55' - NAIL AND CAP EAST SIDE OF 24" BUTTERNUT

AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE
OF THE POSITION OF THE ORIGINAL CORNER.

Signed by

EDWARD W. REED

Date JUNE 18, 1999

Surveyor's Michigan License No. 33985

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

