



LIBER 5 PAGE 35

034953

RECORDED
HILLSDALE CO. MICH.

00 OCT 11 AM 10:41

HILLSDALE COUNTY REMONUMENTATION
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970SURVEY &
REMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp & File Number

For corners in

HILLSDALE

(County)

ADAMS TWP.

Located In:

Corner Code #

1. Public Land Survey

T6S

R2W

D-11

T

R

T

R

T

R

2. Property Controlling
in Section

S

T

R

S

T

R

3. Miscellaneous
Property in Sec.

S

T

R

S

T

R

4. Lot No. , Recorded Plat

5. Private Claims

I, Frederick J. Cutcher, in a field survey on Sept. 15, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO, Robert Clark, Jr., Apr. 1825: Set Quarter Post; Sassafras 7" South 2 lks.; Beech 14"

S. 76° E. 30 lks.

Geo. Mark: Survey #596, Mar. 1871; stake, Butternut 14" S. 70° W. about 100 lks.; W. Oak 6" N. 6-1/2° E. about 125 lks.

Geo. Mark: Survey #930, May 30, 1882; stone with brick, Hickory 10" N. 1° E. 144-1/2 lks.

Geo. Mark: Survey #945, Apr. 1883; 1/4 Post on N. line Section 32.

Geo. Mark: Survey #1002, June 1885; Stone & brick, Hickory 10" N. 3/4° E. 144 lks.

Robert E. Burris, Sr.: LCRC L. 1, P. 303, June 5, 1973, Set R.R. Spike (see LCRC).

Keyno Shellenbarger: LCRC L. 646, P. 100, Dec. 27, 1991, (could not find R.R. spike. Set 1/2" iron rod w/cap from Burris' references).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1/2" x 18" iron with worn cap at road surface. All but one reference from above two LCRC's remain.

Dug at position of iron. Nothing else found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced 1/2" x 18" iron with 3/4" x 30" iron with remonumentation cap in monument box and is accepted as the best available evidence of the position of the original corner.

2.5' N. of centerline Bacon Road.

Found P.K. Util. Pole N. 77° E. 103.48'

Found P.K. Util. Pole N. 57° W. 58.53'

Set Nail & Spotter in R.R. tie post N. 22° E. 33.35'

Set iron w/cap South 27.97'

Signed by Frederick J. Cutcher DateSurveyor's Michigan License No. 24592