



LIBER 3 PAGE 101  
HILLSDALE COUNTY  
REMONUMENTATION

RECORDED 107767  
HILLSDALE CO. MICH.

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

DEC 21 AM 11 14

For corners in

Hillsdale  
(County)  
Fayette Twp.

Located In:

Corner Code #

1. Public Land Survey T 6S R 3W B-3  
T R  
T R  
T R  
2. Property Controlling S T R  
in Section S T R  
3. Miscellaneous S T R  
Property in Sec. S T R

Frederick J. Cutcher  
REG. OF DEEDS

SURVEY &  
MONUMENTATION

JAN 30 1996

Register of Deeds Stamp & File Number  
COMMISSION

4. Lot No. , Recorded Plat  
5. Private Claims

Frederick J.

Cutcher

December 18, 1995

I, Frederick J. Cutcher, in a field survey on December 18, 1995 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Survey, April 28, 1825, Robert Clark, Jr.: Set post; Elm 16 in.  
S. 50° E. 34; W. Oak 9 in. S. 63½° W. 80.

County Surveyors Record 1110, January 13, 1890: Stake, 9½ North.

T. Clow, Ringenberg Eng., April, 1985: ½" iron bar 90.6' North of centerline U.S. 12;  
P.K. E. side fence cor. post S. 35° W., 52.08'; P.K. E. side 6" Maple S. 50° W., 36.84';  
P.K. S.E. side dbl. 12" Ash S. 60° W., 29.42'; Iron bar West 33.0'; P.K. East side 18"  
Maple N. 10° W., 68.60'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron rod with cap #15103 about 4" below road surface.

Four of above references were found.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3	7	8	9	10	11	12							
4	18	17	16	15	14	13							
5	19	20	21	22	23	24							
6	30	29	28	27	26	25							
7	31	32	33	34	35	36							
8													
9													
10													
11													
12													
13													

Fayette Twp.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced iron rod with cap #15103 with 3/4"x36" iron rod with cap (County issue) and is accepted as the best available evidence of the position of the original corner.

4'± West of centerline of N/S road.

Nail N.E. side twin 18" Ash N. 66° W., 31.25'.

Nail N.E. side twin 18" Maple N. 15° W., 69.0'.

Fd. nail on E. side 6" Maple S. 43° W., 36.81'.

Fd. nail E. side R.R. tie corner post S. 30° W., 52.0'.

Nail S.W. side 18" Elm S. 76° E., 44.25'.

Signed by Frederick J. Cutcher  
Surveyor's Michigan License No. 24592

Date December 18, 1995