

LIBER 3 PAGE 155 118423
HILLSDALE COUNTY REMONUMENTATION
AND CORNER RECOGNITION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

TECCRDED ... DIALE DO. MICH.

'96 DEC 20 AM 9 10

For corners in	(
Hillsdale	Located In:	Corner Code ≠	Judy Venjands
(County) Hillsdale Twp.		•	REG. OF DEEDS
Public Land Survey	T 65 R 3W	B-13	NEG. VI DEEDG
	T R		SURVEY &
	T R T R		REMONUMENTATION
2. Property Controlling	S R		
	S T R		SEP 0 3 1999
	S T R		Register of Deeds Stamp & File Number
Property in Sec.	\$ T R		SECTION
4. Lot No, Rec	orded Plat		
5. Private Claims			A B C D E F G H I J K L N
			2 6 5 4 3 - 2 - 1 -
Frederick J.			3
	4 7 - 8 - 9 - 10 - 11 - 12 - 12 - 13 - 13 - 13 - 13 - 13		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned			
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land			
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law: established, re-established, monumented, re-monumented, recovered, found as			
expressed below:			10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and range, may be recorded			
on this certificate.			$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
A. Description of original mo	nument and accessories an	d/or subsequent restoration	n:
Original Government Survey by Clark, 1823: 18" Beech N. 55° E. 27 1/2 lks; 8" Beech			
N. 41° W. 62 Lks.			
Records of Ringenberg: T. Clow found 1/2" iron bar, May, 1984; 4.5' N. of centerline; N. 1/4 Post Section 6, T7S, R3W is East 48.79'; N. 10° W. 61.64' P.K. E. side 4" Cherry;			
East 48.79' R.R. spike; S. 15° E. 39.71' P.K. E. side 10" Oak; South 24.70' P.K. W. side			
4" cedar; S. 45° W. 55.56' P.K. E. side Southerly double walnut.			
LCRC Liber 1, Page 325 #3818, August 13, 1973 by Robert Burris RLS #19563; Found iron bar			
in road; N. 70° E. 63 side of 8" Oak; N. 75			. 30° E. 39.88° P.K. in E. pole.
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:			
On 11/15/96 I found a	1/2" iron at road s	surface agreeing wi	th remaining references.
One of the LCRC witnesses remained and all of the witnesses cited by Clow in 1984 were			
found.			
	•		
			locating the position of the corner:
monument box and is a	con rod with Hillsda coented as the hest	lie County Remonume	ntation bar with cap in a of the position of the original
corner.	scepted as alle best	available evidence	or the position of the original
4.5' N. of centerline			h.
R.R. spike East 48.86 (B-1 T7S, R3W) (48.80 = Measured). S.W. corner house foundation N. 70° E. 159.5'.			
Top center telephone stanchion S. 63° E. 86.02'.			
Nail & spotter W. side 12" Oak S. 15° E. 39.55'.			
Nail & spotter N.W. s	ide 12" twin walnut	S. 50° W. 54.72'.	
Center 6" cedar South	24.0°.		The second of th
Signed by Irederick	1. artcher	Date	December 19, 1996
Frederick J./Cutcher			
Surveyor's Michigan License	NO. <u>27332</u>		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197
			REVISED JAN., 198