

HILLSDALE COUNTY  
REMONUMENTATION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

107578

RECORDED

HILLSDALE CO. MICH.

'95 DEC 15 PM 1 03

Judy Vornjandt  
REG. OF DEEDSSURVEY &  
MONUMENTATION

JAN 30 1996

Register of Deeds Stamp &amp; File Number

COMMISSION

For corners in

Hillsdale

(County)

Located In:

Corner Code =#

Fayette Twp.

1. Public Land Survey

T 6 S R 3 W

E-5

T R

T R

T R

T R

2. Property Controlling  
In Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

Frederick J.

Cutcher

I, in a field survey on November 12, 1995

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Corner common to Sections 8, 9, 16 &amp; 17, Town 6 South, Range 3 West.

Original Government Survey, 1825, Robert Clark Jr.: Set post; W. Oak 9 in. N.  $17\frac{1}{2}^{\circ}$  W., 3.65; B. Oak 16 in. S.  $3\frac{1}{2}^{\circ}$  W., 2.17.Survey 1077, March 19, 1889, R.J. Coryell: Stone; White Oak 13 S.  $7-3/4^{\circ}$  W.,  $286\frac{1}{2}$ , old bearing.No date, Ringenberg Eng.:  $3/4$ " iron on line with fence East; Nail S.W. side P.P. N.  $30^{\circ}$  E., 50.05'; 17.3' W. of St. sign post.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. spike at road surface, 4'± West of centerline N/S road, in line with centerline gravel road to West. No fence visible to East in marsh area.

Found nail in N.W. side P.P. N.  $40^{\circ}$  E., 50.30'. No other references were found.

A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1	
3												
4	7		8		9		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												

Fayette Twp.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced R.R. spike with  $3/4$ "x36" iron rod with cap (County issue) in monument box and is accepted as the best available evidence of the position of the original corner.

3.8' West of centerline N/S road, in centerline of road to West.

Found nail N.E. side P.P. N.  $40^{\circ}$  E., 49.22'.Stop sign S.  $70^{\circ}$  W., 46.6'.MGU gas marker S.  $25^{\circ}$  E., 55.9'.N. end CMP N.  $73^{\circ}$  W., 60.5'.Signed by Frederick J. Cutcher  
Frederick J. Cutcher  
Surveyor's Michigan License No. 24592

Date December 4, 1995