

ACCEPTED BY THE HILLSDALE COUNTY
SURVEY PEER GROUP AS THE OFFICIAL
CORNER UNDER MICHIGAN PUBLIC ACT 345
OF 1970 AT A MEETING HELD ON
12/15/95
AL RINGENBERG, CO. REP.

LIBER 3 PAGE 96

HILLSDALE COUNTY
REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

107582

RECORDED

HILLSDALE CO. MICH.

'95 DEC 15 PM 1 04

For corners in

Hillsdale

(County)

Fayette Twp.

Public Land Survey

Located In:

Corner Code #

T 6 S R 3 W

G-5

T R

T R

T R

S T R

S T R

S T R

S T R

2. Property Controlling
in Section

3. Miscellaneous

Property in Sec.

4. Lot No. , Recorded Plat

5. Private Claims

Frederick J.

Cutcher

in a field survey on November 14, 1995

Do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Corner common to Sections 9, 10, 15 & 16, T6S, R3W

A. Description of original monument and accessories and/or subsequent restoration:

Original Government Survey, 1825, Robert Clark, Jr.: Set stake; W. Oak 7 in. N. 20 $\frac{1}{2}$ ° E., 46; W. Oak 5 in. S. 51 $\frac{1}{2}$ ° W., 30 $\frac{1}{2}$.

Survey 1079, March 27, 1889, R.J. Coryell: Stone & iron; Y. Oak 12 N. 11° E., 89 $\frac{1}{2}$ lks. (old bearing).

A.J. Hatt, January 23, 1964: Set 3/4" iron; P.K. P.P. N. 20° W., 43.9'; P.K. in N.W. side 12" Maple S. 30° W., 45.82'; P.K. S.W. side 24" Oak S. 10° E., 34.78'.

Max W. Walter, December 12, 1967: 3/4" iron pipe; N.W. cor. house S. 24° W., 75.40'; P.P. N. 37° W., 43.90'; 24" Oak S. 19° E., 34.78'; 12" Maple S. 51° W., 45.82'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. spike at road surface, found 3/4" iron pipe 15" below.

Four of above references were found.

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

Fayette Twp.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced R.R. spike and 3/4" iron pipe with 3/4"x36" iron rod with cap (County issue) in monument box and is accepted as the best available evidence of the position of the original corner.

9' West of centerline road to North, in intersection of E/W road.

N.W. cor. house S. 24° W., 75.44'.

Nail in P.P. N. 37° W., 43.70'.

Nail in 36" Oak S. 19° E., 34.60'.

Nail in 24" Maple S. 60° W., 46.16'.

Signed by Frederick J. Cutcher
Frederick J. Cutcher
Surveyor's Michigan License No. 24592

Date December 5, 1995