SURVEY & REMONUMENTATION

LIBER 3 PAGE 11

5 Private Claims

DEC 1 5 1993

87769

RECORDED P LES DALE CO. MICH.

'93 DEC 8 PM 4 42

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Luby Vanzandt REG. OF DEEDS For corners in HILLSDALE Corner Code ## Located In: (County) F-11. F-13 68 R Public Land Survey R R R Т S T ... R 2. Property Controlling S ____ T ___ R ____ in Section S ____ T __ R . . . S ___ T ___ R Miscellaneous Register of Deeds Stamp & File Number Property in Sec.

. 19 **93** John E. Maxson 8 December in a lield survey on ... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

__ , Recorded Plat ___ _ _

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original, monument and accessories and/or subsequent restoration:

GLO, 1823, 17 Wood, 935E, 45 1ks 19 Wood, NBW, 39 1ks Co Sur 1871, Stone Stone, North, 50 1ks

F-13 GLO, 1823, 12 Beech, N52E, 39 Tks 13 Beech, 1125W, 65 1ks Co Sur 1871, Stone . Stone, North, 50 1ks 12 Sycamore, N49E, 50 1ks

10 Sycamore, N71W, 80 1ks

GLO. 1823, 16 Oak, \$46W, 58 1ks 15 Oak, S61E, 23 Tks Co Sur 1868, Stone Original Witnesses LCRC, 1972, Hatt, L1, P133 Iron pipe

10

11

12

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-13

Found 1/2" Iron pipe and one witness stone from 1871 record 33 North Accepted as a careful and faithful perpetuation of the original Corner

Found RR Spike and one witness stone from 1871 record 33 North Accepted as a careful and faithful perpetuation of the original Corner

Found Iron pipe as witnessed in Hatt. LCRC, and Accepted as a careful and faithful reestablishment of the original Corner

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

· F-13 E-11 Reset 5/8 x 36 rebar w/cap in Reset 5/8 x 36 rebar w/cap in Reset 5/8 x 36 rebar w/cap in mon. box mon. box 76.39 12"0ak 33.00' Stone Post S20E 32.15 RR tie Fnc Post Horth North 64.81' 87.25 S32W 26"0ak 31.25 Stone Pillar 355E 60"0ak South 24.44' 1180E 111,56' Utility, Box 844W 45.85 14"Hickory P.Pole 344W 24"Twin Cherry H89W 33.53' 6"Cedar 362W 62.85' 15"Walnut 1172E 68.49'

Surveyor's Michigan License No.



8 December, 1993 Date