SUFIVEY & REMONUMENTATION

DEC 1 5 1993

LIBER 3 PAGE 3

Property in Sec.

Lot No. _____, Recorded Plat

COMMISSION

87702

STOORDED THOSE WALE OD, MICH.

REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

'93 DEC 8 AM 8 47

or corners in	rising Kequi	^	
Hillsdale	Located In:	Corner Code :##	Guerry Vamily
(County)		Comer Code 37	REG. OF DEEDS
. Public Land Survey	т <u>8S</u> в 1W т 8S в 1W	G-13 H-13	
·	T R		
	T A		
Property Controlling	S T R		
in Section	S R		
Miscellaneous	S T D		

andt

Register of Deeds Stamp & File Number

5.	Private Claims					•		
ı	R.Timothy Tietsema	in a field august a	_ 1	Novemb	er 12		93	

S ____ T R

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

A. Description of original monument and accessories and/or subsequent restoration:

1823-GLO: Set original corner 65 links (42.90') East of Post

between Sec. 03 & 04, T9S, R1W.

Ringenberg Records (date unknown) Fnd Stone w/"X" on top

14" Maple N40W 40.0'

NW Bldg Cor S40E 66.3' NE Cor Sec 4 T9S, R1W WEST 42.8'

12/9/1970 Kurzy: Fnd large Stone, Replaced w/Iron

7/17/1980 A. Ringenberg LS#15103: Fnd Boat Spike

NW Bldg Cor S55E 65.94'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-13)

Found Boat Spike from the following:

1" Iron Pipe WEST 43.20' (NW Cor. Sec. 3, T9S, R1W) 24" Maple N07W 30.84' NW Bldg Cor S40E 65.90'

H-13)

Elec. Pole

Iron

Found 1" Iron Pipe from the following:

1823-GLO: Set Original Corner.

S55W 68.00' WEST 38.38'

7/17/1980 Allen Ringenberg LS#15103: Fnd Iron Pipe

Utility Pole S75W 68.95'

1/2" IR WEST 38.36'

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13) Section Corner 33 & 34, T8S, R1W Found Boat Spike per A. Ringenberg's Records (LS#15103), and is accepted as a careful and faithful reestablishment of the position of the original corner. Replaced with a 1" Iron Rod with Hillsdale County Remonumentation Cap.

PK Nail 24" Maple N60W 56.19' PK Nail 22" Maple N20W 75.66'

NW Bldg Cor

NE Bldg Cor

S40E 65.90' WEST 77.82'

H-13) <u>Section Corner 34, T9S, R1W</u> Fnd 1" Iron Pipe per A. Ringenberg's Records (LS#15103) and is accepted as a careful and faithful reestablishment of the position of the original corner. Replaced with a 1" Iron Rod with Hillsdale County Remonumentation Cap.

Nail Utility Pole - S75W 68.95' PK Nail Utility Pole S65E 192.82' PK Nail Dbl 10"Birch N65W 225.22" PK Nail 24" Maple N45W 181.99"

1/2" Iron Rod

WEST 38.36'

Date December 7, 1993

1" IP (NW Cor. Sec. 3) T9S, R1VV) WEST 43.20" Signed by _ Surveyor's Michigan Libense No 120712 * NO. 20712

FRED IND SURY

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975