



034941

RECORDED
HILLSDALE CO. MICH.

00 OCT 11 AM 10:31

LIBER 5 PAGE 23

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

HILLSDALE

(County)

Located In:

Corner Code #

1. Public Land Survey

T 8S R 1W F-11

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

SURVEY &
REMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Jeffrey A. Bieszk, in a field survey on 6 Oct. 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Ziba Swan (1824)
14" Beech N44W 19 lks
18" Beech S20E 23 lks

Geo Mark (1869) survey #512
not found set in (1876) survey #734
Stone and Brick, Stone and Brick
South 50 lks

Robert Burris LCRC L1-P401
Found R.R Spike on Line with fence
to the South 3.2 ft. South centerline road
PK nail Power Pole S45E 64.28 ft.
PK nail R.R. tie fence South 22.42 ft.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. spike as witnessed by Burris, dug under R.R. spike and found nothing. Accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box

Nail w/tag Power Pole	S 65 E	64.18 ft.
PK North Side Road	North	12.81 ft.
PK cl Road	N 85 E	15.26 ft.,
PK cl Road	S 85 W	15.00 ft.



Signed by _____
Surveyor's Michigan License No. 41093

Date OCTOBER 11, 2000