

FEB 16 1999

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners IOSCO

REMONUMENTATION CORNER
Located In: Corner Code #

1. Public Land Survey

T 24N R 9E 4

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous
Property in Sec.

S T R

S T R

4. Lot No. , Recorded Plat

5. Private Claims

98-53

STATE OF MICHIGAN
IOSCO COUNTY
FILED

10 DEC 98 2:55 P.M.

BONITA M. COYLE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, WILLIAM E. WOODS P.S. , in a field survey on NOV 17 , 19 98 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1843: ORIGINAL GOVERNMENT NOTES

SET POST

8" SPR. PINE N 10° W 38 LK.

7" SPR. PINE N 36° E 37 LK.

NOTE: SUPERVISOR'S PLAT OF VAN ETTAN LAKESIDE LIBER 11 PAGES 27-29 AND INTERLAKE PARK LIBER 8 PAGE 38 SUBDIVISIONS SHOWS THE 1/4 CORNER WHICH IS 6 CHAINS 396' NORTH OF THIS CORNER, BUT DOES NOT SHOW THE MEANDER CORNER.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

GOVERNMENT SET MEANDER CORNER 396.0 FEET SOUTH OF 1/4 CORNER

1 SET WITNESS CORNER 151.21 FEET SOUTH OF 1/4 CORNER AND BEING 244.79 FEET NORTH OF MEANDER CORNER



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

5/8 BAR WITH REMON. CAP.

16" OAK S 05° W 7.49

8" OAK S 30° E 8.34

8" WHITE PINE N 50° E 17.49

10" RED PINE N 20° W 20.94

ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 9-22-98

James H. Hanger

Signed by

William E. Woods

Date

12-9-98

WILLIAM E. WOODS P.S.

Surveyor's Michigan License No. 25882