

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Form with fields for Iron (County), Located In, Corner Code #, and numbered sections 1-5 for survey details.

Register of Deeds Stamp & File Number

Grid table with columns A-M and rows 1-13, containing numerical data for registration.

I, Stephan J. Szyszkoski, in a field survey on 15 05/06/13 SMC 05/09/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 18) West 1/16 corner between Sections 18 and 19. Not previously monumented. The original plat of this township gives distances 20.00 chains east to the Quarter corner and 19.70 chains west to the Section corner.

(SMC between Gov't Lots 7 and 8) Being the intersection of the westerly shoreline of the Michigamme River with the North 1/16 line of Section 20. 1960 - The position was monumented by Billy D. Buckler RLS 14.44 chains east of 1/16 corner #3 on a line parallel with the North line of the Section. Set 1"IDx48" I.pipe. No witnesses.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 18) Established the position for the corner on the Section line between Quarter corner 1355.81' east and Section corner 1335.48' west, proportionate to the original plat dimensions. From the position thus established, I found a channel-type iron fence post from which an old wire fence runs northerly, apparently marking a long-standing approximation of the corner, S72°W 50.8 feet distant, which I did not accept as marking the position for the corner.

(SMC) The 1960 monument was not recovered. I regard the 1960 position as an approximation as the method used to establish the position was not correct. Established the position for the corner at the intersection of the West shoreline of the Menominee River (the current shoreline at this location seeming to have been unaffected by the 1893 Mansfield cave-in immediately to the north and by the subsequent relocation of the river) with the North 1/16 line, being a straight line between 1/16 corners #3 and #5. Placed a WITNESS CORNER to the SMC 27 feet west of the apparent ordinary high water mark on the west shore. The Witness corner is 973.30 feet easterly from 1/16 corner #3.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 12" Sugar S58°E 36.5' mrkd "1/16S BT" 4" Sugar S27°E 14.9' do 5" Spruce S71°W 8.45' do 5" Ironwood N43°W 52.0' do Set sq'd cedar post adjacent. E= 7904367.085 N= 148891.128

(SMC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap being a Witness Corner on the N1/16 line 27 feet west of the corner position. Set measuring nail with MDNR tag in the side of: 6" Ash N46°E 35.3' mrkd "WC BT" 3" Ash S55°E 17.9' do 6" Ash S17°W 21.7' do 13" Elm S23°W 21.3' do Set sq'd cedar post adjacent. E= 7905869.028 N= 148469.605

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum). Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.635 m.

Signed by [Signature] Surveyor's Michigan License No. 33986

Date 07/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

