

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 18 T 43N R 31W	8
	S 18 T 43N R 31W	12
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 03/07/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 18) West 1/16 corner, Section 18. Not previously monumented.

(12-Sec. 18) South 1/16 corner, Section 18. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 18) Established the position for the corner on a straight line between Quarter corner
1330.56' west and Center of Section 18 1337.93' east, the position being 20.0 chains, proportionate
to the dimensions derived from the original plat, west of the Center of the Section. From the
position thus established, I found a 1/2" ID I.pipe with elbow, loosely set, by persons unknown,
S31°E 38' distant, which I did not accept as marking the position for the corner.

(12-Sec. 18) Established the position for the corner midway and on a straight line between Quarter
corner 1322.57' south and the Center of Section 18 1322.57' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. measuring nail with MDNR tag in the side of:	(12) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
8" Sugar North 22.6' mrkd "1/16S BT"	5" Cedar N40°E 5.8' mrkd "1/16S BT"
8" Sugar S86°E 21.4' do	6" Cedar S53°E 3.55' do
6" Sugar S35°E 27.6' do	7" Cedar S64°W 11.5' do
8" Sugar S36°W 14.8' do	8" Cedar N09°W 5.65' do
Set sq'd cedar post adjacent.	Set sq'd cedar post adjacent.
E= 7904375.049 N=149696.538	E= 7904781.492 N= 149288.638

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).

Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.635 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

